

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ORIGINAL

FIELD NOTES

OF

THE DEPENDENT RESURVEY OF

A PORTION OF THE SOUTH BOUNDARY,

(EIGHTH STANDARD PARALLEL SOUTH)

A PORTION OF THE SUBDIVISIONAL LINES,

THE SUBDIVISION OF SECTIONS 28, 33, AND 34

AND

THE RETRACEMENT OF A PORTION OF THE

WESTERLY FRONTAGE ROAD RIGHT OF WAY LINE OF INTERSTATE 15,

AND

A PORTION OF THE

EASTERLY RIGHT OF WAY LINE OF OLD HIGHWAY 91

IN

TOWNSHIP 40 SOUTH, RANGE 13 WEST

OF THE SALT LAKE MERIDIAN
IN THE STATE OF UTAH

EXECUTED BY

Larry V. Judd
Cadastral Surveyor

Under special instructions dated **April 4, 2001**, approved **April 4, 2001**,
which provided for the surveys included under Group Number **928**, and
assignment instructions dated **April 6, 2001**

Survey commenced **May 7, 2001**
Survey completed **June 6, 2001**

INDEX DIAGRAM

Township 40 South , Range 13 West

6	5	4	3	2	1
7	8	9	10	11	12
18	17	16	15	14	13
19	20	21	22	23	24
30	29	14 15	10	26	25
31	32	14 28	10 27	6	25
		15	8	6	
		12 13	8	6	
		11 33	7 34	6 35	36
		5 4	3		

The Subdivision of Section 28.....Page 15
 The Subdivision of Section 33.....Page 18
 The Subdivision of Section 34.....Page 24
 Retracement of the westerly right of way line.....Page 25
 Retracement of the easterly right of way line.....Page 28

TOWNSHIP 40 SOUTH, RANGE 13 WEST, SALT LAKE MERIDIAN, UTAH

The following field notes are those of the dependent resurvey of a portion of the south boundary, (eighth standard parallel south) a portion of the subdivisional lines, the subdivision of sections 28, 33, and 34, and the retracement of a portion of the westerly frontage road right of way line of Interstate 15 and the easterly right of way line of old highway 91, in Township 40 South, Range 13 West, Salt Lake Meridian, Utah.

History of Surveys

Surveyed by		Retr. or Resurveyed by	
SOUTH BOUNDARY (Eight Standard Parallel South)			
Portion	J. Bausman	1870	
Portion	Bailey and Burrill	1877	
All	Jenkins and West	1897	Jenkins and West 1897
Portion			H.D. Heist 1902
Portion			R.C. Yundt 1949
Portion			C.P. Sylvester 1978-79
Portion			R.A. Zaninovich 1990
EAST BOUNDARY (Guide Meridian)			
All	H.D. Heist	1902	
All			Nelson and Stumm 1911
Portion			R.A. Zaninovich 1987
WEST BOUNDARY			
All	H.D. Heist	1902	
NORTH BOUNDARY			
Portion	J. Gorlinski	1870	
All	H.D. Heist	1902	H.D. Heist 1902
All			A. Nelson 1930
SUBDIVISION			
Portion	J. Bausman	1870	
Portion	J. Gorlinski	1870	
Portion	Bailey and Burrill	1877	
Portion	H.D. Heist	1902	H.D. Heist 1902
Remonumentation			F.D. Reynolds 1968

PRIVATE SURVEYS

Bulloch Brothers Engineering of Cedar City Utah, executed a survey in Section 32, with the plat dated 6/28/93, and recorded.

Ballard and Campbell Land Surveyors of Hurricane Utah, executed a survey in Section 28, with the plat dated 3/19/91, and recorded.

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
EIGHTH STANDARD PARALLEL SOUTH
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Burton Land Surveying of Washington Utah, executed two different surveys in Section 33, with the first plat dated 7/28/99, and recorded, and the second plat dated 3/16/01.

Record information from a right of way plat of old highway 91, (1929-1930) exact date unknown, shows a tie from a center line station to the found 1/4 section corner of sections 27 and 28. During the execution of this survey, no remaining evidence of the 1/4 section corner was found. The calculated point based upon the tie appears to be incorrect. The point does not fit well in relation of the other found corners in the area, and was therefore not used.

The survey was executed in accordance with the specifications set forth in the Manual of Surveying Instructions, 1973, and the Special Instructions for Group No. 928, Utah, dated April 4, 2001.

The directions of lines were determined by references to true meridians established by the Global Positioning System, utilizing Real Time Kinematic (RTK) survey techniques observed with Trimble 4700 model Global Positioning System receivers along with Pacific Crest radio equipment, with a portion of the angles and distances measured with a Topcon series 4B total station.

Preliminary to the resurvey, retracement and survey, the lines of the prior surveys were retraced and a diligent search was made for all corners and other calls of record. Identified corners were remonumented in their original positions. The retracement data were thoroughly verified and only the true line field notes are given herein.

Geodetic control was derived from National Geodetic Survey triangulation station "MESA", with published data as follows:

Latitude 37° 02' 03.894650" N. Longitude 113° 15' 01.353150"W. N.A.D. 1983 (1994)

The geographic position of the standard 1/4 section corner of sections 3 and 34, on the south boundary of the township as determined by a tie made to National Geodetic Survey triangulation station "MESA", is as follows:

Latitude 37° 15' 31.787" N Longitude 113° 18' 05.888" W.
N.A.D. 1983

Dependent Resurvey of a Portion of the South Boundary,
(Eighth Standard Parallel South)
T. 40 S., R.13 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey Executed by
J. Bausman in 1870, the Retracement by H.D. Heist in 1902
and the Resurvey by C.P. Sylvester in 1978-79.

Beginning at the 1/4 section corner of sections 3 and 34, monumented with an iron post, 2 1/2 inches diameter, firmly set, in a mound of stone, with the brass cap marked as described in the official record of the resurvey by C.P. Sylvester in 1978-79.

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
EIGHTH STANDARD PARALLEL SOUTH
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

The corner falls on a gradual southeast slope.

From this corner, National Geodetic Survey triangulation station "MESA", monumented with a standard brass disk set in solid sandstone bears S. 10° 22' 39" E., (forward bearing) and N. 10° 20' 47" W., (back bearing) for a distance of 1258.866 chains.

N. 89° 40.1' W., on the south boundary of the township.

39.296 Point for the closing corner of sections 33 and 34.

From this point, a sandstone, 16x12x5 inches set in a scattered mound of stone alongside the remains of an old cedar post, with a nail set directly under the rock, bears S. 0° 05.4' W., 0.021 chains distance. No marks were found on the rock.

From which the original bearing tree.

A juniper, 8 inches diam., with scribes visible through mostly healed blaze, bears N. 81° W., 1.431 chains distance (record 1.47 chains).

No remaining evidence of the NE bearing tree was found.

At the point of intersection

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

T40S R13W
CC
S33|S34
T41S
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Raise a mound of stone, 3 ft. base, by 1 ft. high to the north.

From which the original bearing tree with a new tie, bears N. 81° 49' W., 1.43 chains distance.

41.003 The corner of sections 3 and 4, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with a steel fence post alongside, and with the brass cap marked as described in the official record of the resurvey by C.P. Sylvester in 1978-79.

The corner is set in the bottom of a small swell, which drains to the northeast.

N. 89° 49.1' W., continuing with new measurement.

18.296 Point for the E 1/16 section corner of section 33 only.

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
 EIGHTH STANDARD PARALLEL SOUTH
 T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

Set a steel fence post, 5 1/2 feet long, driven 5 feet in the ground, with an aluminum post, 30 inches long, 2 1/2 inches diameter, set over the top, and with the aluminum cap marked:

T40S R13W
E 1/16 S33
 T41S
 2001

The corner falls in sandy soil, susceptible to drifting, approximately 100 feet west of a dirt trail road, 8 feet wide, bears S. 20° E., and N. 20° W.

Set a steel fence post, 6 1/2 feet long alongside the aluminum post.

- 20.288 The E 1/16 section corner of section 4 only, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 8 inches above ground, with the brass cap marked as described in the official record of the resurvey by C.P. Sylvester in 1978-79.

N. 89° 51.2' W., continuing with new measurement.

- 18.012 Point for the 1/4 section corner of section 33 only.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

T40S R13W
1/4 S33
 T41S
 2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Raise a mound of stone, 2 ft. base, by 1 ft. high to the north.

The corner falls in sandy soil, on a gradual southeast slope.

- 20.266 The standard 1/4 section corner of section 4 only, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with the brass cap marked as described in the official record of the resurvey by C.P. Sylvester in 1978-79.

The corner falls on a gradual east slope.

N. 89° 47.3' W., continuing with new measurement.

- 7.747 Point for the E - W 1/64 section corner of section 33 only.

Set a steel fence post, 5 1/2 feet long, driven 5 feet in the ground, with an aluminum post, 30 inches long, 2 1/2 inches diameter, set over the top, and with the aluminum cap marked:

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
EIGHTH STANDARD PARALLEL SOUTH
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

T40S R13W
E-W 1/64 S33
T41S
2001

The corner falls in sandy soil, on a gradual west slope.

Set a steel fence post, 5 1/2 feet long, 1 foot west of the aluminum post.

- 17.749** The W 1/16 section corner of section 33 only, monumented with a rebar, 1/2 inch diameter, firmly set, projecting 4 inches above ground, set at the corner of fences, projecting north and west. There was no identifying cap attached to the rebar. Origin unknown.

At the rebar.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with the aluminum cap marked:

T40S R13W
W 1/16 S33
T41S
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

The corner falls in sandy soil, on a gradual west slope.

- 20.597** The W 1/16 section corner of section 4 only, monumented with an iron post, 2 1/2 inches diameter, firmly set, 3 feet below ground, with the brass cap pitted and unreadable except for the date; 1978.

The corner falls, 1 foot east of the end of a fence, extending west, in an area of drifting sand dunes.

N. 89° 48.0' W., beginning new measurement.

- 17.155** The closing corner of sections 32 and 33, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 10 inches above ground, with the brass cap marked as described in the official record of the resurvey by C.P. Sylvester in 1978-79.

The corner falls in a fence line, projecting east and west, 11 feet south of the south edge of 1400 north street, a paved road, 28 feet wide.

N. 89° 42.8' W., beginning new measurement.

- 3.464** The corner of sections 4 and 5, monumented with a Washington County survey monument, a brass cap, 3 inches diameter, firmly set flush with the ground, with the brass cap marked as

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

set flush with the ground, with the brass cap marked as described in the official record of the resurvey by C.P. Sylvester in 1978-79.

The corner falls in line with a fence to the east, and 11 1/2 feet south of the south edge of 1400 north street, a paved road, 28 feet wide.

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 40 S., R. 13 W., Salt Lake Meridian, Utah

Reestablishment of the Survey executed by
T.C Bailey in 1877

From the 1/4 section corner of sections 34 and 35, monumented with a lava stone, 26x16x12 inches, firmly set, plainly marked 1/4 on the west face, with a large mound of stone to the west, and with a steel fence post set in the mound of stone.

At the corner point

Set a aluminum post, 30 inches long, 2 1/2 inches diameter, 16 inches in the ground, set in a mound of stone, 4 ft. base to top of the aluminum cap marked:

T40S R13W
1/4
S34|S35
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Deposit the marked stone alongside the aluminum post.

From this corner

The corner of sections 2, 3, 34 and 35, bears S. 0° 09.8' W., 39.872 chains distance, monumented with a Washington County survey monument, an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with the brass cap marked as described in the official record of the resurvey by C.P. Sylvester in 1978-79.

N. 0° 02.6' E., between sections 34 and 35.

39.833 The corner of sections 26, 27, 34 and 35, monumented with a Washington County survey monument with brass cap, set flush with the ground in a collar of stone, with a steel fence post to the north, and with the brass cap marked:

40
27|26
34|35
13
1973

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

A granite stone, 30x12x8 inches, plainly marked with 3 notches on the east edge and 1 notch on the south edge was found on the east side of the pillar in the collar of stone.

Raise a mound of stone, 3 ft. base, by 2 ft. high to the west.

The corner is set on top of a ridge, bears northwest and southeast.

Deposit the marked stone in the mound of stone.

This monument is accepted as the best available evidence of the position of the original corner.

Reestablishment of the Survey executed by
H.D. Heist on 1902

From the closing corner of sections 33 and 34, on the south boundary of the township; hereinbefore described.

N. 0° 05.4' E., between sections 33 and 34.

39.081 The 1/4 section corner of sections 33 and 34, monumented with a sandstone 16x10x4 inches, firmly set, dimly marked 1/4 on the west face and with a plainly marked cross (X) chiseled on top of the rock.

At the corner point

Set a stainless steel post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the brass cap marked:

T40S R13W
1/4
S33|
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Deposit the marked stone alongside the aluminum post.

Raise a mound of stone, 2 ft. base, by 1 ft. high to the west.

The corner falls at the corner of fences projecting, east, west and north.

Due to the lottings created in sections 33 and 34, which are based upon the survey executed by H.D. Heist in 1902, and shown on the plat of survey dated February 26, 1904, the 1/4 section corner set common to sections 33 and 34, will now function only for the 1/4 section corner of section 33 only.

N. 0° 03.1' W., beginning new measurement.

0.763 Point for the 1/4 section corner of section 34 only.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

T40S R13W
1/4
|S34
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, alongside the aluminum post.

The corner falls, 6 feet west of a fence, projecting north and south.

19.990 Point for the N 1/16 section corner of section 33 only, not monumented.

39.980 The corner of sections 27, 28, 33 and 34, monumented with a Washington County survey monument, a brass disk, 3 inches diameter set in a concrete pillar, 6 inches diameter, and in a large mound of stone, with the brass cap marked:

40
28|27
33|34
13
1973

A granite stone, 30x12x8 inches, plainly marked with 3 notches on the east edge and 1 notch on the south edge was found on the east side of the pillar in the mound of stone.

The corner is set on top of a ridge, bears northwest and southeast.

This monument is accepted as the best available evidence of the position of the original corner.

From the corner of sections 26, 27, 34 and 35.

S. 89° 54.0' W., between sections 27 and 34.

20.060 Point for the E 1/16 section corner of sections 27 and 34.

Set a Bathy Brand T iron, 18 inches long, set 20 inches in the road bed of State Road No. 17, with an aluminum cap, 3 1/4 inches diameter, attached and marked:

E 1/16 S27
S34
2001

The corner falls, 2.6 feet west of the east edge of the road set in the asphalt, and 0.90 feet east of the center of the white stripe on the easterly edge of the road.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

- 40.120 The 1/4 section corner of sections 27 and 34, monumented with a Washington County survey monument, a brass disk, 3 inches diameter, set in a concrete pillar 6 inches diameter, projecting 14 inches above ground, with the brass disk marked:

40
1/4 27
34
13
1973

No remaining evidence of the original marked stone or bearing trees were found.

The corner falls in sandy soil on a gradual north slope.

This monument is accepted as a careful and faithful determination of the position of the original 1/4 section corner by proportionate measurement.

S. 89° 53.2' W., beginning new measurement.

- 20.060 Point for the W 1/16 section corner of sections 27 and 34.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 6 inches in the ground, set in a mound of stone, 5 ft. base to top of the aluminum cap marked:

W 1/16 S27
S34
2001

The corner falls, 7 ft. east of the top edge of a lava rim, 8 ft. high, bears N. 30° E., and S. 30° W.

- 40.120 The corner of sections 27, 28, 33 and 34.

N. 0° 07.0' E., between sections 27 and 28.

- 20.045 Point for the S 1/16 section corner of sections 27 and 28, not monumented.

- 29.985 Intersect the easterly right of way line of old highway 91.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked, ROW S27 S28 2001, with intersecting lines.

From this corner

Right of way station 1085+00, bears N. 38° 23.7' E., 6.761 chains distance, monumented with an iron post, 2 inches diameter, firmly set, projecting 3 inches above ground, with the brass cap marked: STA 1085+00 ELEV 3796.81 1964.

with continuous measurement

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

- 40.090** The 1/4 section corner of sections 27 and 28, monumented with a rebar, 1/2 inch diameter, firmly set, projecting 5 inches above ground, with a yellow plastic cap attached and marked B & C Eng. LS 4490.

At the rebar

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 12 inches in the ground, set in a mound of stone, 4 ft. base to top of the aluminum cap marked:

T40S R13W
1/4
S28|S27
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Deposit the rebar inside the aluminum post.

This monument is accepted as a careful and faithful determination of the position of the 1/4 section corner by proportionate measurement.

- 40.823** Intersect the easterly right of way line of old highway 91.

From this point

A right of way station, bears N. 38° 12.3' E., 4.184 chains distance, monumented with an iron post, 2 inches diameter, firmly set, projecting 3 inches above ground, with the old style brass cap unmarked.

with continuous measurement

- 60.135** Point for the N 1/16 section corner of sections 27 and 28.

Set a rebar, 3/4 inch diameter, 8 inches long, drilled 7 inches into solid rock, with a 3 1/4 inches diameter aluminum cap attached and marked:

N 1/16
S28|S27
2001

Raise a mound of stone, 3 ft. base, by 2 ft. high to the east of the rebar and cap.

The corner falls within a rock outcrop.

- 80.180** The corner of sections 21, 22, 27 and 28, monumented with a Washington County survey monument, a brass disk, 3 inches diameter, set in a concrete pillar 6 inches diameter, firmly set, projecting 10 inches above ground in a mound of stone, with the brass disk marked:

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

40
21|22
28|27
13
1973

A granite stone, 30x12x10 inches, plainly marked with 3 notches on the east edge and 2 notches on the south edge was found on the east side of the pillar in the mound of stone.

From which the original bearing trees.

A juniper, 14 inches diam., marked 1/4 BT,
bears S. 22° E., 1.07 chains distance.
(Record S. 24° E., 1.11 chains)

No remaining evidence of the original NE or NW bearing trees were found.

The corner falls S. 85° E., 16.0 feet from the corner of fences, projecting north and west.

This monument is accepted as the best available evidence of the position of the original corner.

From the closing corner of sections 32 and 33, on the south boundary of the township; hereinbefore described.

N. 0° 11.3' W., on the line between sections 32 and 33.

18.936 Point for the S 1/16 section corner of sections 32 and 33.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground, with the aluminum cap marked:

S 1/16
S32|S33
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 5 1/2 feet long, 0.50 feet east of the aluminum post.

The corner falls 3 feet east of a fence line, projecting north and south.

38.974 The 1/4 section corner of sections 32 and 33, monumented with a sandstone, 20x12x8 inches, loosely set, dimly marked 1/4 S, and with a cross (X) on the face of the rock.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

T40S R13W
1/4
S32|S33
2001

No remaining evidence of the original bearing trees were found.

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 5 1/2 feet long, alongside the aluminum post.

The monument falls, 9.4 feet west of a fence line, projecting north and south.

N. 0° 11.8' E., beginning new measurement.

- 39.924** Point for the corner of sections 28, 29, 32 and 33, at proportionate distance. No remaining evidence of the original corner was found.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with the aluminum cap marked:

T40SR13W
S29|S28
S32|S33
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 5 1/2 feet long, 0.50 feet west of the aluminum post

Raise a mound of stone, 2 ft. base, by 1 ft. high to the west.

From this corner, south 0.048 chains distance, a rebar, 1/2 inch diameter, firmly set with a yellow plastic cap attached and marked BBE ENG., which is set at the corner of fences, projecting south and west. This rebar was set based on an incorrect proportion and therefore not utilized.

From the corner of sections 27, 28, 33 and 34.

N. 89° 52.8' W., between sections 28 and 33.

- 20.016** The E 1/16 section corner of sections 28 and 33, monumented with a rebar, 5/8 inch diameter, firmly set with a yellow plastic cap attached and marked BURTON RLS 160267, and with a steel fence post alongside the rebar.

This monument is accepted as a careful and faithful determination of the E 1/16 section corner position.

At the rebar

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

E 1/16 S28
S33
2001

Deposit the rebar and cap inside the aluminum post.

The corner falls on a gradual west slope, 25 feet west of the top of a ridge and road, 10 feet wide, bears N. 25° W., and S. 25° E.

- 23.257** Intersect the easterly right of way line of old highway 91, not monumented.

From this point, right of way station 1055+00, bears S. 36° 38.5' W., 0.620 chains distance, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 4 inches above ground, with the post leaning back into the right of way fence, with the brass cap removed. The point of plumb was tied.

From this same point

A right of way station, bears N. 36° 38.5' E., 4.532 chains distance, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 12 inches above ground, with the old style brass cap unmarked

- 31.991** Intersect the westerly frontage road, right of way line of Interstate 15, not monumented.

From this point, right of way station 1050+00, bears S. 38° 11.6' W., 2.812 chains distance, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 3 inches above ground, with the brass cap marked: STA 1050+00 ELEV 3749.64 1964.

From this same point

Right of way station 1060+00, bears N. 38° 11.6' E., 12.340 chains distance, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 4 inches above ground, with the brass cap marked: STA 1060+00 ELEV 3752.28 1964.

- 40.032** The 1/4 section corner of sections 28 and 33, monumented with a rebar 1/2 inch diameter, firmly set, with a yellow plastic cap attached and marked B & C ENG LS 4092. Buried alongside the rebar was a sandstone, 24x14x7 inches, plainly marked 1/4 S on one face.

At the rebar

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

T40S R13W
1/4 S28
S33
2001

No remaining evidence of the original bearing trees were found.

Deposit the rebar inside the aluminum post.

Deposit the marked stone alongside the aluminum post.

The monument falls at the corner of fences, projecting north and east.

This monument is accepted as the best available evidence of the position of the original corner.

N. 89°58.8' W., beginning new measurement.

39.980 The corner of sections 28, 29, 32 and 33.

N. 0° 01.6' W., beginning new measurement

39.924 The 1/4 section corner of sections 28 and 29, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 6 inches above ground, with the brass cap marked as described in the official record of the remonumentation survey by F.D. Reynolds in 1968.

From which the original bearing trees.

A juniper, 30 inches diam., marked S28 BT,
bears S. 61° E., 48 links distance.

The SW bearing tree was found down and dead at record bearing and distance.

The corner falls at the corner of fences, projecting north and west.

N. 0° 03.3' W., beginning new measurement.

39.919 The corner of sections 20, 21, 28 and 29, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with the brass cap marked as described in the official record of the remonumentation survey by F.D. Reynolds in 1968.

From which the original bearing trees.

A juniper, 8 inches diam., cut off at 4 feet high
standing dead, with scribe marks visible,
bears S. 42° E., 12 links distance.

A juniper, 16 inches diam., with scribe marks visible,
through mostly healed blaze, bears N. 52° W., 13 1/2
links distance.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES
T. 40 S., R 13 W., SALT LAKE MERIDIAN UTAH

Chains

From the corner of sections 21, 22, 27 and 28.

S. 89° 50.5' W., between sections 21 and 28.

- 40.200** The 1/4 section corner of sections 21 and 28, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with the brass cap marked as described in the official record of the remonumentation survey by F.D. Reynolds in 1968.

From which the original bearing trees.

A juniper, 16 inches diam., scribed S28 BT
bears S. 22° 23' E., 1.72 chains distance.

A juniper, 16 inches diam., with scribe marks visible,
on dead limb, bears N. 53° W., 1.19 chains
distance.

S. 89° 49.0' W., beginning new measurement.

- 40.020** The corner of sections 20, 21, 28 and 29.

From the corner of sections 28, 29, 32 and 33.

N. 89° 51.8' W., between sections 29 and 32.

- 39.981** The 1/4 section corner of sections 29 and 32, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with the brass cap marked as described in the official record of the remonumentation survey by F.D. Reynolds in 1968.

From which the original bearing trees.

A juniper, 12 inches diam., scribed 1/4 S32 BT
bears S. 62° E., 0.535 chains distance.

A juniper, 10 inches diam., scribed 1/4 S29 BT
bears N. 43° 30' W., 0.685 chains distance.

The corner falls in a fence line projecting east and west.

The Subdivision of Section 28,
T. 40 S., R. 13 W., Salt Lake Meridian, Utah

From the 1/4 section corner of sections 28 and 33.

N. 0° 00.5' W., on the N - S center line of section 28.

- 19.986** Point for the center S 1/16 section corner of section 28.

THE SUBDIVISION OF SECTION 28,
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

Set a steel fence post, 4 feet long, driven 4 feet in the ground, with an aluminum post, 30 inches long, 2 1/2 inches diameter set over the top, and with the aluminum cap marked:

C
S 1/16 | S 28
C
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Raise a mound of stone, 4 ft. base, by 2 ft. high to the west of the aluminum post.

The corner falls in sandy ground, S. 45° W., 1.0 feet from the corner of fences, projecting south and east.

- 39.972** Point for the center 1/4 section corner, at intersection with the E - W center line of section 28.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

T40S R13W
C 1/4
S28
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Raise a mound of stone, 4 ft. base, by 2 ft. high to the west.

The monument falls on a moderate rocky east slope.

- 79.986** The 1/4 section corner of sections 21 and 28.

From the 1/4 section corner of sections 27 and 28.

S. 89° 57.1' W., on the E - W center line of section 28.

- 0.576** Intersect the westerly frontage road, right of way line of Interstate 15, not monumented.

- 20.058** Point for center E 1/16 section corner of section 28.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 16 inches in the ground, set in a mound of stone 3 feet base, to top of the aluminum cap marked:

E 1/16
C ——— C
S28
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

THE SUBDIVISION OF SECTION 28,
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

The corner falls on flat ground.

- 40.116 The center 1/4 section corner of section 28.
80.106 The 1/4 section corner of sections 28 and 29.

From the E 1/16 section corner of sections 28 and 33.

N. 0° 03.3' E., on the N - S center line of the SE 1/4, of section 28.

- 4.346 Intersect the easterly right of way line of old highway 91, monumented with a rebar, 5/8 inch diameter, firmly set, projecting 3 inches above ground, with a yellow plastic cap attached and marked, BURTON RLS 160267.

At the rebar

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground with the aluminum cap marked, ROW S28 2001, with lines of intersection.

Deposit the rebar and cap inside the aluminum post.

The monument falls at the end of fence along the right of way, extending S. 38° W.

- 15.257 Intersect the westerly frontage road, right of way line of Interstate 15, monumented with a rebar, 1/2 inch diameter, firmly set, projecting 3 inches above ground, with a yellow plastic cap attached and marked, B & C ENG. LS 4091.

At the rebar

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground with the aluminum cap marked, ROW S28 2001, with lines of intersection.

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Deposit the rebar and cap inside the aluminum post.

The monument falls in a fence line projecting north and south, 1 1/2 feet north of the intersection of the north and south fence and the fence along the right of way, bears N. 38° E., and S. 38° W.

- 20.016 The SE 1/16 section corner, monumented with a rebar, 1/2 inch diameter, firmly set, projecting 3 inches above ground, with a yellow plastic cap attached and marked, B & C ENG. LS 4401.

This monument is accepted as a careful and faithful determination of the position of the SE 1/16 section corner position.

At the rebar

THE SUBDIVISION OF SECTION 28,
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 18 inches in the ground with the aluminum cap marked:

SE 1/16
S28
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Deposit the rebar and cap inside the aluminum post.

The monument falls, N. 45° E., 0.80 feet from the corner of fences, projecting south and west.

40.032 The center E 1/16 section corner of section 28.

From the point for the S 1/16 section corner of sections 27 and 28.

N. 89° 57.9' W., on the E - W center line of the SE 1/4 of section 28.

7.771 Intersect the easterly right of way line of old highway 91.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground with the aluminum cap marked, ROW S28 2001, with lines of intersection.

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, east of the aluminum post in the right of way fence.

The monument falls N. 52° W., 1.3 feet from the right of way fence, bears N. 38° E., and S. 38° W.

16.297 Intersect the westerly frontage road, right of way line of Interstate 15, not monumented.

20.037 The SE 1/16 section corner of section 28.

40.074 The center S 1/16 section corner of section 28.

The Subdivision of Section 33,
T. 40 S., R. 13 W., Salt Lake Meridian, Utah

From the 1/4 section corner of section 33 only, on the south boundary of the township; hereinbefore described.

N. 0°00.4' W., on the N - S center line of section 33.

19.090 Point for the center S 1/16 section corner of section 33, not monumented.

THE SUBDIVISION OF SECTION 33
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

- 39.038** Point for the center 1/4 section corner, at intersection with the E - W center line of section 33.

Set a steel fence post, 5 1/2 feet long, driven 5 feet in the ground with an aluminum post, 30 inches long, 2 1/2 inches diameter, set over the top, and with the aluminum cap marked:

T40S R13W
C 1/4
S33
2001

Set a steel fence post, 6 1/2 feet long, 1 foot east of the aluminum post.

The corner falls in sandy ground on shifting sand dunes.

- 56.454** Intersect the easterly right of way line of old highway 91.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground with the aluminum cap marked, ROW S33 2001, with lines of intersection.

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 1 foot north of the aluminum post.

The monument falls, 65 feet south of the east edge of the pavement of the frontage road, 24 feet wide, bears N 37° E., and S. 37° W.

- 59.032** Point for the center N 1/16 section corner of section 33.

Set a steel fence post, 5 1/2 feet long, driven 5 feet in the ground, with an aluminum post, 30 inches long, 2 1/2 inches diameter, set over the top, and with the aluminum cap marked:

C
N 1/16 | S 33
C
2001

The monument falls in sandy ground, 2 feet west of the frontage road right of way fence, on the east side of Interstate 15.

- 68.783** Intersect the westerly frontage road right of way line of Interstate 15.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground with the aluminum cap marked, ROW S33 2001, with lines of intersection.

Deposit a magnet, enclosed within an orange plastic case at the base of the aluminum post.

Set a steel fence post, 5 1/2 feet long, 1 foot south in the right of way fence.

THE SUBDIVISION OF SECTION 33
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

79.026 The 1/4 section corner of sections 28 and 33.

From the 1/4 section corner of section 33 only, on the east side of the section.

N. 89° 53.4' W., on the E - W center line of section 33.

20.034 Point for the center E 1/16 section corner of section 33.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

$$\begin{array}{c} \text{E } 1/16 \\ \text{C} \frac{\quad}{\quad} \text{C} \\ \text{S33} \\ \text{2001} \end{array}$$

The monument falls on a gradual west slope, approximately 30 feet west of the top of a ridge, bears north and south.

40.068 The center 1/4 section corner of section 33.

53.027 Intersect the easterly right of way line of old highway 91.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground with the aluminum cap marked, ROW S33 2001, with lines of intersection.

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 5 1/2 feet long, 1 foot west of the aluminum post.

The monument falls, 46 feet east of the east edge of the pavement of the frontage road, 24 feet wide, bears N 37° E., and S. 37° W.

60.131 Point for the center W 1/16 section corner of section 33, not monumented.

63.441 Intersect the westerly frontage road, right of way line of Interstate 15.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground with the aluminum cap marked, ROW S33 2001, with lines of intersection.

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 5 1/2 feet long, 1.6 feet east of the aluminum post in the right of way fence.

80.194 The 1/4 section corner of sections 32 and 33.

THE SUBDIVISION OF SECTION 33
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

From the center E 1/16 section corner of section 33.

N. 0° 01.7' W., on the N - S center line of the NE 1/4, of section 33.

- 19.992** Point for the NE 1/16 section corner, at intersection with the E - W center line of the NE 1/4 of section 33.

Set a rebar, 8 inches long, 3/4 inch diameter, drilled 7 inches into solid sandstone with an aluminum cap, 3 1/4 inches diameter, attached and marked:

NE 1/16
S33
2001

Raise a mound of stone, 3 feet base by 2 feet high, north of the rebar and cap.

The monument falls on a moderate northeast slope, 47 feet west of the bottom of a drainage, 3 feet wide, drains N. 25° W.

- 39.984** The E 1/16 section corner of sections 28 and 33.

From the point for the N 1/16 section corner of section 33 only.

N. 89° 53.1' W., on the E - W center line of the NE 1/4 of section 33.

- 20.025** The NE 1/16 section corner of section 33.

- 38.125** Intersect the easterly right of way line of old highway 91.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground with the aluminum cap marked, ROW S33 2001, with lines of intersection.

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 6 feet long, 1 foot west of the aluminum post.

The monument falls, 48 feet east of the east edge of the pavement of the frontage road of Interstate 15.

- 40.050** The center N 1/16 section corner of section 33.

From the E 1/16 section corner of section 33 only, on the south boundary of the township; hereinbefore described.

N. 0° 02.5' E., on the N - S center line of the SE 1/4, of section 33.

- 39.052** The center E 1/16 section corner of section 33.

THE SUBDIVISION OF SECTION 33
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

From the W 1/16 section corner of section 33 only, on the south boundary of the township; hereinbefore described.

N. 0° 05.9' W., on the N - S center line of the SW 1/4 of section 33.

- 19.013** The SW 1/16 section corner of section 33, monumented with a rebar, 5/8 inch diameter, firmly set, projecting 4 inches above ground, with a yellow plastic cap attached and marked, BURTON RLS 160267.

This monument is accepted as a careful and faithful determination of the position for the SW 1/16 section corner.

At the rebar.

Set a steel fence post, 5 1/2 feet long, driven 5 feet in the ground with an aluminum post, 30 inches long, 2 1/2 inches diameter set over the top, and with the aluminum cap marked:

SW 1/16
S33
2001

Deposit the rebar inside the aluminum post.

Set a steel fence post, 6 1/2 feet long, 1 foot west of the aluminum post.

The corner falls on flat sandy ground.

- 29.475** Intersect the easterly right of way line of old highway 91, not monumented.

- 39.006** Point for the center W 1/16 section corner of section 33.
-

From the point for the center S 1/16 section corner of section 33.

S. 89° 58.9' W., on the E - W center line of the SW 1/4 of section 33.

- 10.016** Point for the CE-SW 1/64 section corner of section 33.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with the aluminum cap marked:

CE - SW
1/64
S33
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 6 1/2 feet long, 0.50 feet east of the aluminum post.

THE SUBDIVISION OF SECTION 33
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

The monument falls on flat sandy ground.

20.032 The SW 1/16 section corner of section 33.

27.844 Intersect the easterly right of way line of old highway 91.

This point was determined by extending the line from monument station 1010+00 through monument station 1006+1/27 at intersection with the E-W center line of the SW 1/4 of section 33. Stations 1006+1/27 and 1010+00 are hereinafter described in the retracement notes of the easterly right of way of old highway 91.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with the aluminum cap marked: ROW S33 2001, with lines of intersection.

Deposit a magnet, enclosed within an orange plastic case at the base of the aluminum post.

Set a steel fence post, 5 1/2 feet long, 1 foot west.

The monument falls, 45 feet east of the east edge of the frontage road, 24 feet wide, bears N. 37° E., and S. 37° W.

39.111 Intersect the westerly frontage road right of way line of Interstate 15.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground with the aluminum cap marked: ROW S33 2001, with lines of intersection.

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

From this corner, right of way station 1000+00, bears S. 38° 24.4' W., 2.187 chains distance, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 3 inches above ground, with the brass cap marked: STA 1000+00 ELEV 3706.39 1964.

40.064 The S 1/16 section corner of sections 32 and 33.

From the E-W 1/64 section corner of section 33 only, on the south boundary of the township; hereinbefore described.

N. 0° 03.1' W., on the N - S center line of the SE 1/4, SW 1/4, of section 33.

19.053 The CE-SW 1/64 section corner of section 33.

The Subdivision of Section 34,
T. 40 S., R. 13 W., Salt Lake Meridian, Utah

THE SUBDIVISION OF SECTION 34,
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

From the 1/4 section corner of sections 3 and 34 on the south boundary of the township; hereinbefore described.

N. 0°37.2' E., on the N - S center line of section 34.

- 39.843** Point for the center 1/4 section corner, at intersection with the E - W center line of section 34.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

T40S R13W
C 1/4
S34
2001

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

Set a steel fence post, 5 1/2 feet long, 1 foot south of the aluminum post.

The monument falls, 3 feet north and 13 feet west from the corner of fences projecting, east, west and south.

- 79.373** The 1/4 section corner of sections 27 and 34.

From the 1/4 section corner of section 34 and 35.

N. 89° 40.0' W., on the E - W center line of section 34.

- 20.261** Point for the center E 1/16 section corner of section 34.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with the aluminum cap marked:

E 1/16
C ——— C
S34
2001

Set a steel fence post, 1 foot south of the aluminum post.

The monument falls on flat sandy ground, 66 feet north of a fence line, projecting N. 87° W., and S. 87° E.

- 40.522** The center 1/4 section corner of section 34.

- 60.353** Point for the center W 1/16 section corner of section 34.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 10 inches in the ground, set in a mound of stone, 4 feet base to top of the aluminum cap marked:

W 1/16
C ——— C
S34
2001

RETRACEMENT OF A PORTION OF THE WESTERLY FRONTAGE ROAD
 RIGHT OF WAY LINE OF INTERSTATE 15,
 T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

Deposit a magnet, enclosed within a orange plastic case at the base of the aluminum post.

The monument falls on top of a ridge, on a gradual SE slope, 53 feet south of a fence line projecting, S. 86° W., and N. 86° E.

- 80.184 The 1/4 section corner of section 34 only.

From the center E 1/16 section corner of section 34.

N. 0° 19.8' E., on the N - S center line of the NE 1/4 of section 34.

- 39.681 The E 1/16 section corner of sections 27 and 34.

From the center W 1/16 section corner of section 34.

N. 0° 17.1' E., on the N - S center line of the NW 1/4, of section 34.

- 39.373 The W 1/16 section corner of section 34.

Retracement of a Portion of the
 westerly frontage road right of way line of Interstate 15,
 T. 40 S., R. 13 W., Salt Lake Meridian, Utah.

From the point of intersection on the E - W center line of the SW 1/4 of section 33; hereinbefore described.

N. 38° 24.4' E., on the westerly right of way line, through section 33.

- 0.120 A right of way station, monumented with an iron post, 2 inches diameter, firmly set in concrete, flush with the ground, with the brass cap unmarked.

N. 38° 11.7' E., beginning new measurement.

- 7.080 A right of way station, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 1 inch above ground, with the brass cap unmarked.

N. 38° 11.9' E., beginning new measurement.

- 5.652 Right of way station, 1010+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 1 inch above ground, with the brass cap marked: STA 1010+00 ELEV 3699.71 1964.
-

RETRACEMENT OF A PORTION OF THE WESTERLY FRONTAGE ROAD
 RIGHT OF WAY LINE OF INTERSTATE 15,
 T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

N. 38° 11.6' E., beginning new measurement.

- 12.604 The monument at the point of intersection with the E - W center line of section 33; hereinbefore described.

N. 38° 11.6' E., beginning new measurement.

- 2.912 Right of way station. 1020+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 1 inch above ground, with the brass cap marked: STA 1020+00 ELEV 3708.10 1964.

N. 38° 11.6' E., beginning new measurement.

- 7.207 Right of way station, 1025+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 10 inches above ground, with the brass cap marked: STA 1025+00 ELEV 3720.41 1964.

N. 38° 12.4' E., beginning new measurement.

- 7.571 Right of way station, 1030+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 8 inches above ground, with the brass cap marked: STA 1030+00 ELEV 3731.23 1964.

N. 38° 11.9' E., beginning new measurement.

- 7.574 Right of way station, 1035+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 4 inches above ground, with the brass cap marked: STA 1035+00 ELEV 3738.21 1964.

N. 38° 12.0' E., beginning new measurement.

- 10.393 Right of way station, 1041+8/85, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 6 inches above ground, with the brass cap marked: STA 1041+8/85 ELEV 3749.64 1964.

N. 38° 10.1' E., beginning new measurement.

- 2.133 The monument at the point of intersection with the N - S center line of section 33; hereinbefore described.

From this corner, right of way station 1050+00, bears N. 38° 10.1' E., 10.196 chains distance, monumented with an iron post, 2 inches diameter, firmly set, projecting 3 inches above ground, with the brass cap marked: STA 1050+00 ELEV 3742.45 1964.

RETRACEMENT OF A PORTION OF THE WESTERLY FRONTAGE ROAD
 RIGHT OF WAY LINE OF INTERSTATE 15,
 T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

THROUGH SECTION 28

From the monument at the point of intersection with the N - S center line of the SE 1/4 of section 28; hereinbefore described.

From this corner, right of way station 1060+00, bears S. 38° 14.2' W., 7.044 chains distance, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 4 inches above ground, with the brass cap marked: STA 1060+00 ELEV 3752.28 1964.

N. 38° 14.2' E., continuing along the westerly frontage road right of way line of Interstate 15, through section 28.

- 0.527** Right of way station, 1065+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 10 inches above ground, with the brass cap marked: STA 1065+00 ELEV 3763.69 1964.

N. 38° 12.4' E., beginning new measurement.

- 5.527** The point of intersection with the E - W center line of the SE 1/4 of section 28; hereinbefore described.

N. 38° 12.4' E., beginning new measurement.

- 2.044** Right of way station, 1070+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 14 inches above ground, with the brass cap marked: STA 1070+00 ELEV 3783.44 1964.

N. 38° 11.6' E., beginning new measurement.

- 7.552** Right of way station, 1075+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 10 inches above ground, with the brass cap marked: STA 1075+00 ELEV 3782.67 1964.

N. 38° 09.5' E., beginning new measurement.

- 7.591** Right of way station, 1080+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 4 inches above ground, with the brass cap marked: STA 1080+00 ELEV 3802.20 1964.

N. 38° 13.3' E., beginning new measurement.

- 7.556** Right of way station, 1085+00, monumented with an iron post, 2

RETRACEMENT OF A PORTION OF THE EASTERLY
RIGHT OF WAY LINE OF OLD HIGHWAY 91
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

inches diameter, firmly set in concrete, projecting 6 inches above ground, with the brass cap marked: STA 1085+00 ELEV 3803.81 1964.

N. 38° 12.3' E., beginning new measurement.

- 0.749** The point of intersection with the E - W center line of section 28; hereinbefore described.
-

N. 38° 12.3' E., beginning new measurement.

- 0.934** The point of intersection with the line between sections 27 and 28; hereinbefore described.
-

Retracement of a Portion of the easterly
right of way line of old highway 91,
T. 40 S., R. 13 W., Salt Lake Meridian, Utah.

From the monument at the point of intersection with the E - W center line of the SW 1/4 of section 33; hereinbefore described.

N. 36° 41.5' E., on the easterly right of way line of old highway 91, through section 33.

- 0.228** Right of way station, 1006+1/27 monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 6 inches above ground, with the brass cap marked: STA 1006+1/27 ELEV 3680.09 1964.
-

N. 36° 41.5' E., beginning new measurement.

- 5.650** Right of way station, 1010+00 monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 6 inches above ground, with the brass cap marked: STA 1010+00 ELEV 3682.60 1964.
-

N. 36° 40.5' E., beginning new measurement.

- 7.168** The point of intersection on the N - S center line of the SW 1/4 of section 33; hereinbefore described.
-

N. 36° 40.5' E., beginning new measurement.

- 8.358** A right of way station, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 4 inches above ground, with the brass cap marked: STA ELEV 3698.54 1964.
-

RETRACEMENT OF A PORTION OF THE EASTERLY
RIGHT OF WAY LINE OF OLD HIGHWAY 91
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

N. 36° 40.0' E., beginning new measurement.

- 3.511** The monument at the point of intersection with the E - W center line of section 33; hereinbefore described.

N. 36° 40.0' E., beginning new measurement.

- 5.416** A right of way station, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 22 inches above ground, with the old style brass cap unmarked.

N. 36° 40.3' E., beginning new measurement

- 13.435** Right of way station, 1035+00 monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 2 inches above ground, with the brass cap marked: STA 1035+00 ELEV 3728.08 1964.

N. 36° 47.5' E., beginning new measurement.

- 2.836** The monument at the point of intersection with the N - S center line of section 33; hereinbefore described.

N. 36° 47.5' E., beginning new measurement.

- 3.214** The monument at the point of intersection with the E - W center line of the NE 1/4 of section 33; hereinbefore described.

From this corner, right of way station 1040+00, bears N. 36° 47.5' E., 1.636 chains distance, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 3 inches above ground, with the brass cap marked: STA 1040+00 ELEV 3734.16 1964.

THROUGH SECTION 28

From the monument at the point of intersection with the N - S center line of the SE 1/4 of section 28, hereinbefore described.

From this corner, a right of way station, bears S. 37° 33.5' W., 0.886 chains distance, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 12 inches above ground, with the old style brass cap unmarked.

N. 37° 33.5' E., on the easterly right of way line of old highway 91, through section 28.

RETRACEMENT OF A PORTION OF THE EASTERLY
RIGHT OF WAY LINE OF OLD HIGHWAY 91
T. 40 S., R. 13 W., SALT LAKE MERIDIAN, UTAH

Chains

- 1.531** Right of way station, 1060+00, monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 4 inches above ground, with the brass cap marked: STA 1060+00 ELEV 3759.58 1964.
-
- N. 38° 09.4' E., beginning new measurement.
- 15.154** Right of way station, 1070+00 monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 5 inches above ground, with the brass cap marked: STA 1070+00 ELEV 3759.58 1964.
-
- N. 38° 05.5' E., beginning new measurement.
- 3.217** The monument at the point of intersection with the E - W center line of the SE 1/4 of section 28; hereinbefore described.
-
- N. 38° 05.5' E., beginning new measurement.
- 12.012** Right of way station, 1080+00 monumented with an iron post, 2 inches diameter, firmly set in concrete, projecting 10 inches above ground, with the brass cap marked: STA 1080+00 ELEV 3796.81 1964.
-
- N. 38° 23.7' E., beginning new measurement.
- 0.614** The monument at the point of intersection with the line between sections 27 and 28; hereinbefore described.
-

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

Name	Capacity
Jim Webster	Engineering Technician

CERTIFICATE OF SURVEY

I, *Larry V. Judd, Cadastral Surveyor*, hereby certify upon honor that, in pursuance of special instructions bearing the date of the 4th day of April, 2001, I have **executed a dependent resurvey of a portion of the south boundary (Eighth Standard Parallel South), a portion of the subdivisional lines, the subdivision of sections 28, 33 and 34 and the retracement of a portion of the westerly frontage road right of way line of Interstate 15, and a portion of the easterly right of way line of old highway 91, in Township 40 South, Range 13 West,**

of the *Salt Lake Meridian*, in the State of *Utah*, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

7/30/01
Date

Date

Larry V. Judd
(Cadastral Surveyor)

(Cadastral Surveyor)

CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT
Salt Lake City, Utah

The foregoing field notes of the **dependent resurvey of a portion of the south boundary (Eighth Standard Parallel South), a portion of the subdivisional lines, the subdivision of sections 28, 33 and 34 and the retracement of a portion of the westerly frontage road right of way line of Interstate 15, and a portion of the easterly right of way line of old highway 91, in Township 40 South, Range 13 West, executed by Larry V. Judd, Cadastral Surveyor** having been critically examined and found correct, are hereby approved.

July 31, 2001
Date

Daniel W. Webb
(Chief Cadastral Surveyor for Utah)