

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

ORIGINAL

# FIELD NOTES

OF  
THE DEPENDENT RESURVEY OF  
PORTIONS OF THE NORTH BOUNDARY,  
AND SUBDIVISIONAL LINES,  
AND THE DEPENDENT RESURVEY  
OF THE  
SUBDIVISION OF SECTIONS 3, 4, 9, AND 10,  
(ORIGINALLY SURVEYED BY THE THREE MILE METHOD),  
AND THE SURVEY OF THE  
SUBDIVISION OF SECTIONS 3, 4, 9, AND 10,  
IN  
TOWNSHIP 3 SOUTH, RANGE 3 WEST  
OF THE UINTAH SPECIAL MERIDIAN  
IN THE STATE OF UTAH

EXECUTED BY

*Jerry L. Thomas*  
*Cadastral Surveyor*

Under special instructions dated *May 20, 1994*, approved *May 20, 1994*, which provided for the surveys included under Group Number *818*, and assignment instructions dated *June 15, 1994*.

Survey commenced *July 26, 1994*

Survey completed *September 1, 1994*

**INDEX DIAGRAM**

Township 3 South, Range 3 West

		3	1		
6	5 17	4 11	3 6	2	1
		16	10		
7	8 14	9 9	10 5	11	12
		13	7		
18	17	16	15	14	13
19	20	21	22	23	24
30	29	28	27	26	25
31	32	33	34	35	36

The Resurvey of the Subdivision of Section 3.....Page 18  
 The Resurvey of the Subdivision of Section 4.....Page 20  
 The Resurvey of the Subdivision of Section 9.....Page 23  
 The Resurvey of the Subdivision of Section 10.....Page 26  
 The Survey of the Subdivision of Section 3.....Page 30  
 The Survey of the Subdivision of Section 4.....Page 31  
 The Survey of the Subdivision of Section 9.....Page 32  
 The Survey of the Subdivision of Section 10.....Page 34

## TOWNSHIP 3 SOUTH, RANGE 3 WEST, UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

The following field notes describe the dependent resurvey of portions of the north boundary, the subdivisional lines, the subdivision of sections 3, 4, 9, and 10, (originally surveyed by the three mile method), and the survey of the subdivision of sections 3, 4, 9, and 10, in Township 3 South, Range 3 West, Uintah Special Meridian, Utah.

The north, south, east, and west boundaries, subdivisional lines and the subdivision of sections utilizing the three mile method were surveyed by D.G. Major in 1882. A portion of the west boundary was resurveyed by A.J. Stewart and A.L. Booth in 1903 and resurveyed by R. Gentry in 1914. The south boundary was resurveyed by J.R. and A.J. Stewart in 1904 and R. Gentry in 1919. Portions of the north boundary, subdivisional lines, and subdivision of sections and all of the east boundary were resurveyed by R. Gentry in 1919.

The survey was executed in accordance with specifications as set forth in the Manual of Surveying Instructions, 1973, and the Special Instructions for Group No. 818, dated May 20, 1994.

The direction of lines were determined by hour angle observations of the sun and Polaris, carried forward by sustained angulation. Distances were determined by electronic measurement.

Preliminary to the resurvey the lines of the original survey were retraced and a diligent search was made for any evidence of the original field note record. Identified corners were remonumented in their original positions; lost corners were restored and monumented at proportionate positions based on the original record. The retracement data were thoroughly verified and only the true line notes are given herein.

The geographic position of the northwest corner of section 4, determined by GPS, which will now function as a B.L.M. control station, is:

Latitude 40° 15' 28.881" N. Longitude 110° 14' 12.980" W.  
N.A.D. 1927.

The mean magnetic declination as determined from numerous readings throughout the survey is: 13 1/2° E.

---

Dependent Resurvey of a Portion of the North Boundary,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

Reestablishment of the Survey Executed by D.G. Major in 1882,  
and the Resurvey by R. Gentry in 1919

---

Beginning at the corner of sections 2, 3, 34, and 35, determined latitudinally by center of right-of-way of Utah State Highway No. 87, and longitudinally by corner of fence, with fences projecting N and W.

DEPENDENT RESURVEY OF A PORTION OF THE NORTH BOUNDARY,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

At the corner point

Drive a nail, 3 inches long, flush with surface of road.

from which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, for a reference monument, bears North, 50 links distance, with magnet at base, with aluminum cap marked T2S R3W S34 RM 1994 33 FT. and an arrow pointing to the corner.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, for a reference monument, bears S. 25° 00' E., 63 links distance, with magnet at base, with aluminum cap marked T3S R3W S2 RM 1994 41.6 FT. and an arrow pointing to the corner.

S. 89° 59' W., between sections 3 and 34, on the north boundary of the township.

Along State Highway No. 87.

**20.055** Point for the E 1/16 section corner of sections 3 and 34, at proportionate distance, falls in State Highway No. 87; there is no remaining evidence of the 1919 resurvey corner.

Drive a nail, 3 inches long, flush with surface of road.

from which,

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, for a reference monument, bears N. 1° 01' E., 47 links distance, with magnet at base, with aluminum cap marked T2S R3W S34 RM 1994 31 FT. and an arrow pointing to the corner.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, for a reference monument, bears S. 0° 12' W., 48 1/2 links distance, with magnet at base, with aluminum cap marked T3S R3W S3 RM 1994 31.9 FT. and an arrow pointing to the corner.

**40.11** Point for the 1/4 section corner of sections 3 and 34, at proportionate distance, falls in State Highway No. 87; there is no remaining evidence of the 1919 resurvey corner.

Drive a nail, 3 inches long, flush with surface of road.

DEPENDENT RESURVEY OF A PORTION OF THE NORTH BOUNDARY,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

from which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, for a reference monument, bears S. 48° 06' E., 71 1/2 links distance, with magnet at base, with aluminum cap marked T3S R3W S3 RM 1994 47.1 FT. and an arrow pointing to the corner.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, for a reference monument, bears S. 55° 22' W., 85 links distance, with magnet at base, with aluminum cap marked T3S R3W S3 RM 1994 56.0 FT. and an arrow pointing to the corner.

**42.50** Utah State Highway No. 87, bears E and curves NW.

**60.165** The W 1/16 section corner of sections 3 and 34, monumented with an iron post, 1 inch diameter, firmly set, 6 inches below mound of earth, with brass cap marked and witnessed as described in the field notes of the 1919 resurvey record.

I remove earth around iron post, exposing 6 inches above ground, and place a mound of stone, 2 1/2 ft. base, 1 1/2 ft. high, north of the iron post.

---

N. 89° 58' W., beginning new measurement.

**20.035** Point for the corner of sections 3, 4, 33, and 34, on the north boundary of the township, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

T2S R3W	
S33	S34
S4	S3
T3S	
1994	

Raise a mound of stone, 2 1/2 ft. base, 1 1/2 ft. high, W of corner.

---

N. 89° 58' W., between sections 4 and 33.

Over rolling land.

**6.00** Lake Fork River, drains SE.

**15.00** Utah asphalt road, curves NE and SW.

DEPENDENT RESURVEY OF A PORTION OF THE NORTH BOUNDARY,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

## CHAINS

**20.035**

The E 1/16 section corner of sections 4 and 33, monumented with an iron post, 1 inch diameter, firmly set, projecting 6 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.

---

N. 89° 58.5' W., beginning new measurement.

**20.035**

Point for the 1/4 section corner of sections 4 and 33, on the north boundary, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner, falls near edge of road.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 30 inches in the ground, with magnet at base, with aluminum cap marked:

T2S R3W  
1/4 S33  
S4  
T3S  
1994

from which

Corner post of board fence, bears N. 62° 00' E., 42 1/2 links distance.

North railroad tie in N and S fence line, bears S. 62° 00' W., 65 links distance.

Corner is located near E edge of paved road, projects S and curves W.

**40.07**

Point for the W 1/16 section corner of sections 4 and 33, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Corner point not monumented.

**50.00**

Intersection of dirt roads, with roads projecting NW, SE, and E.

**60.105**

The corner of sections 4, 5, 32, and 33, monumented with an iron post, 2 inches diameter, firmly set, projecting 8 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.

Geodetic coordinates at this corner was determined by GPS hereinbefore described.

---

Dependent Resurvey of a Portion of the Subdivisional,  
Lines, T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

Reestablishment of the Survey Executed by D.G. Major  
in 1882, and the Resurvey by R. Gentry in 1919

From the corner of sections 10, 11, 14, and 15, monumented with a rusted iron post, 2 inches diameter, firmly set, flush with surface of ground, with brass cap badly defaced.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

T3S R3W	
S10	S11
S15	S14
1994	

Deposit the rusted and broken 1919 resurvey iron post alongside the aluminum post.

Build a reference mound of stone W of aluminum post.

Corner is located 53 links S of E and W fence and 50 links E of N and S fence.

N. 0° 30' W., between sections 10 and 11.

Over nearly level land.

**19.82** Point for the S 1/16 section corner of sections 10 and 11, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

S 1/16	
S10	S11
1994	

Corner is located 8 links S of E and W fence line and 27 links E of N and S fence line.

**39.14** Point selected for the witness corner to the 1/4 section corner of sections 10 and 11.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

## CHAINS

WC  
T3S R3W  
1/4  
S10 ↑ S11  
1994

Corner is located in old E and W fence line and 15 links S. of E - W dirt road.

**39.64** True point for the 1/4 section corner of sections 10 and 11, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner, falls in irrigation ditch where it is impracticable to establish a permanent monument.

**59.46** Point for the N 1/16 section corner of sections 10 and 11, at proportionate distance; there is no remaining of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

N 1/16  
S10 | S11  
1994

Corner is located 24 links E of N and S fence line.

**79.28** The corner of sections 2, 3, 10, and 11, monumented with an iron post, 2 inches diameter, firmly set, projecting 6 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.

N. 0° 27' W., between sections 2 and 3.

Over nearly level land.

**18.00** Point selected for the witness corner to the S 1/16 section corner of sections 2 and 3.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

WC  
S 1/16  
S3 ↑ S2  
1994

**19.74** True point for the S 1/16 section corner of sections 2 and 3, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner; falls in the Lake Fork river bed, draining SE, where it is impracticable to establish a permanent monument.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

## CHAINS

39.48

The 1/4 section corner of sections 2 and 3, monumented with the lower portion of the 1919 resurvey iron post, 1 inch diameter, firmly set, with the broken upper portion nearby.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

T3S R3W  
1/4  
S3 | S2  
1994

Deposit the broken portions of the original iron post alongside the aluminum post.

Set a steel fence post alongside the aluminum post.

Corner is located in NW corner of irrigated field.

---

N. 0° 17' W., beginning new measurement.

19.815

Point for the N 1/16 section corner of sections 2 and 3, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

N 1/16  
S3 | S2  
1994

Raise a mound of stone, 2 1/2 ft. base, 1 1/2 ft. high, W of corner.

39.93

The corner of sections 2, 3, 34, and 35, on the north boundary of the township, hereinbefore described.

---

From the corner of sections 10, 11, 14, and 15.

S. 89° 47' W., between sections 10 and 15.

Over nearly level land.

20.14

Point for the E 1/16 section corner of sections 10 and 15, at proportionate distance determined by using the Grant Boundary Adjustment; there is no remaining evidence of the 1919 resurvey corner.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

E 1/16     S10  
                  S15  
                  1994

Corner is located 3 links W of N and S fence line, and 21 links N of E and W fence line.

N. 89° 50' W., beginning new measurement.

- 20.00** Point for the 1/4 section corner of sections 10 and 15, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set a 6 ft. fence post, 5 ft. in the ground, insert an aluminum post, 30 inches long, 2 1/2 inches diameter, over the fence post, in a mound of stone, 3 ft. base, to top of aluminum cap marked:

T3S R3W  
1/4     S10  
                  S15  
                  1994

Corner is located on S edge of slough, and 41 links N of E and W fence line.

- 40.00** Point for the W 1/16 section corner of sections 10 and 15, at proportionate distance, falls in large swampy area; there is no remaining evidence of the 1919 resurvey corner.

Due to the swampy conditions, it is impractical to set a standard moument; set a steel fence post, 5 ft. long, 2 ft. in the ground.

- 59.25** County asphalt road, bears S and curves NE.

- 60.00** Point for the corner of sections 9, 10, 15, and 16, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

T3S R3W  
S9 | S10  
S16 | S15  
1994

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

from which

A right-of-way marker, an aluminum cap flush with surface of ground,  
marked Duchesne County LS4858 CVL 50 sta 283+41.30 1992,  
bears S. 78° 28' E., 10 links distance.

Corner of fence, with fences projecting N and W, bears S. 70° 07' W.,  
50 links distance.

From this corner, the corner of sections 15, 16, 21, and 22, monumented with an aluminum  
post, 2 inches diameter, firmly set, projecting 4 inches above ground, with aluminum cap  
marked: T3S R3W S15 S16 S21 S22 1990 Duchesne County Survey, bears S. 0° 08' E.,  
80.53 chains distance. This control line was fully retraced and a careful search was made  
for evidence of intervening corners; none of which were recovered.

N. 0° 42' W., between sections 9 and 10.

Over nearly level land.

**19.79** Point for the S 1/16 section corner of sections 9 and 10, at proportionate distance; there is  
no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with  
magnet at base, with aluminum cap marked:

S 1/16  
S9 | S10  
1994

Corner is located 33 links E of N and S fence line.

**39.58** The 1/4 section corner of sections 9 and 10, marked by a shallow hole with rusted metal,  
with an iron post, 36 inches long, 1 inch diameter, filled with concrete, with brass cap  
marked as described in the field notes of the 1919 resurvey record lying nearby. The  
shallow hole with rusted metal is accepted as the best available evidence of the position of  
the 1919 resurvey monument.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with  
magnet at base, with aluminum cap marked:

T3S R3W  
1/4  
S9 | S10  
1994

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

Deposit the portions of broken iron post and brass cap alongside the aluminum post.

---

N. 0° 35' W., beginning new measurement.

- 19.79** Point for the N 1/16 section corner of sections 9 and 10, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

N 1/16  
S9 | S10  
1994

Corner is located 98 links W of N and S fence line, and 60 links S of E and W corral fence.

- 39.58** The corner of sections 3, 4, 9, and 10, monumented an iron post, 2 inches diameter, firmly set, projecting 14 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.

from which

A brass tablet imbedded in a concrete block, with brass tablet marked M-94 Elev 5429 1984, for a bench mark, bears N. 5° 33' W., 2.49 chains distance.

Corner is located in N and S fence line.

---

From the corner of sections 2, 3, 10, and 11.

S. 89° 32' W., between sections 3 and 10.

Over nearly level land.

- 20.03** The E 1/16 section corner of sections 3 and 10, monumented with an iron post, 1 inch diameter, firmly set, projecting 10 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.
- 

N. 89° 44' W., beginning new measurement.

- 20.07** The 1/4 section corner of sections 3 and 10, monumented with an iron post, 1 inch diameter, buried 12 inches below surface of ground, upper portion of iron post, with brass cap was not found.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, in a collar of stone, with aluminum cap marked:

	T3S	R3W
	1/4	<u>S3</u>
		S10
		1994

Deposit the broken piece of iron post alongside the aluminum post.

N. 89° 56' W., beginning new measurement.

**20.10** Point for the W 1/16 section corner of sections 3 and 10, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

	W 1/16	<u>S3</u>
		S10
		1994

**39.60** County asphalt road, bears N and S.

**40.20** The corner of sections 3, 4, 9, and 10.

N. 0° 18' W., between sections 3 and 4.

Over nearly level land.

**2.00** Paved road, bears W. to Arcadia and E to intersection of county asphalt road.

**19.735** Point for the S 1/16 section corner of sections 3 and 4, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

	S 1/16
	S4   S3
	1994

Corner is located 28 links W of N and S center line of county asphalt road, and 30 links E of N and S fence line.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**  
**39.47**

Point for the 1/4 section corner of sections 3 and 4, at proportionate distance, falls in pavement of county asphalt road; there is no remaining evidence of the 1919 resurvey corner,.

Drive a nail, 3 inches long, flush with surface of road.

from which

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears S. 48° 23' E., 75 links distance, with aluminum cap marked T3S R3W S3 RM 1994 49.4 FT and an arrow pointing to the corner.

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears S. 43° 29' W., 51 1/2 links distance, with aluminum cap marked T3S R3W S4 RM 1994 33.9 ft. and an arrow pointing to the corner.

**59.205**

The N 1/16 section corner of sections 3 and 4, monumented with an iron post, 1 in diameter, buried 12 inches below surface of ground, badly rusted and bent.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

N 1/16  
S4 | S3  
1994

Deposit the 1919 resurvey iron post alongside the aluminum post.

Corner is located in center of old N and S trail road, and 43 links W of N and S fence line.

N. 0° 17' W., beginning new measurement.

**14.00** Lake Fork River, drains SE (scaled).

**17.50** Lake Fork River, drains SE (scaled).

**20.255** The corner of sections 3, 4, 33, and 34, on the north boundary of the township, hereinbefore described.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

From the corner of sections of 9, 10, 15, and 16.

S. 89° 51' W., between sections 9 and 16.

Over nearly level land.

- 20.00** The E 1/16 section corner of sections 9 and 16, marked by fragments of the iron post, buried 24 inches below the surface of the ground, the remaining portion of the iron post and brass cap lying nearby. These fragments are accepted as the best available evidence of the 1919 resurvey corner.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

E 1/16      S9    
                  S16  
                  1994

Corner is located 25 links N of E and W fence line.

S. 89° 31' W., beginning new measurement.

- 19.05** Point selected for the witness corner to the 1/4 section corner of sections 9 and 16.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

WC  
T3S R3W  
1/4 ←   S9    
                  S16  
                  1994

Corner is located 17 links N of E and W fence line.

- 20.05** True point for the 1/4 section corner of sections 9 and 16, at proportionate distance, falls in irrigation canal and cannot be monumented; there is no remaining evidence of the 1919 resurvey corner.

- 40.10** Point for the W 1/16 section corner of sections 9 and 16, at proportionate distance, falls in dirt road, bearing E and W; there is no remaining evidence of the 1919 resurvey corner.

Drive a spike, 6 inches long, flush with surface of road

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

from which

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears N. 51° 30' E., 73 links distance, with aluminum cap marked T3S R3W S9 RM 1994 48.2 FT. and an arrow pointing to the corner.

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears S. 39° 00' E., 51 links distance, with aluminum cap marked T3S R3W S16 RM 1994 33.7 FT. and an arrow pointing to the corner.

60.15

The corner of sections 8, 9, 16, and 17, monumented with a rebar, at the center line of a paved road, bearing N and S. This position is harmoniously related to existing 1919 resurvey corners, has long been recognized as the corner by local residents with knowledge of the corner position prior to construction of the county road, and is accepted as the best available evidence of the 1919 resurvey corner position.

from which

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears N. 38° 23' E., 98 links distance, with aluminum cap marked T3S R3W S9 RM 1994 64.7 FT. and an arrow pointing to the corner.

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears N. 37° 50' W., 67 links distance, with aluminum cap marked T3S R3W S8 RM 1994 44.2 FT. and an arrow pointing to the corner.

N. 0° 11' E., between sections 8 and 9.

Over nearly level land.

20.105

Point for the S 1/16 section corner of sections 8 and 9, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

S 1/16  
S8 | S9  
1994

Corner is located in E and W fence line.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

## CHAINS

40.21

The 1/4 section corner of sections 8 and 9, monumented with an iron post, 1 inch diameter, firmly set, projecting 8 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.

Corner is located by fence corner, with fences projecting E. and S.

N. 1° 16' W., beginning new measurement.

19.705

The N 1/16 section corner of sections 8 and 9, monumented with the lower portion of an iron post, 1 inch diameter, filled with concrete, firmly set flush with surface of ground. Upper portion with brass cap cannot be found.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

N 1/16		
S8		S9
1994		

Deposit the remaining portion of the 1919 resurvey iron post alongside the aluminum post.

Corner is located 49 links S of E and W fence line, and 32 1/2 links W of N - S fence line.

N. 1° 25' W., beginning new measurement.

19.46

Point selected for the witness corner to the corner of sections 4, 5, 8, and 9.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

WC		
T3S		R3W
S5	↑	S4
S8		S9
1994		

Corner is located in old E and W fence line.

19.71

True point for the corner of sections 4, 5, 8, and 9, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner, falls in irrigation canal.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

From this corner point, the E 1/16 section corner of sections 5 and 8, monumented with an iron post, 1 inch diameter, firmly set, projecting 8 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record, bears S. 88° 49' W., 19.99 chains distance.

From the corner of sections 3, 4, 9, and 10.

S. 89° 55' W., between sections 4 and 9.

Over nearly level land.

- 20.01** Point for the E 1/16 section corner of sections 4 and 9, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

E 1/16  $\frac{S4}{S9}$   
1994

Corner is located 57 links S of E and W fence line.

- 40.02** Point for the 1/4 section corner of sections 4 and 9, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

T3S R3W  
1/4  $\frac{S4}{S9}$   
1994

Corner is located 32 links S of center line of E and W road, and near N. edge of irrigation canal, flowing E.

- 60.03** True point for the W 1/16 section corner of sections 4 and 9, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner, falls in irrigation canal.

From this point I move North, 10 links distance for a witness corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

WC  
W 1/16  $\frac{S4}{S9}$   
↓  
1994

Witness corner is located 30 links S of center line of E and W road.

**80.04** True point for the corner of sections 4, 5, 8, and 9.

N. 0° 20' W., between sections 4 and 5.

Over nearly level land.

**0.30** Dirt road, bears E and W.

**19.70** Point for the S 1/16 section corner of sections 4 and 5, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner; not monumented.

**39.40** Point for the 1/4 section corner of sections 4 and 5, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

T3S R3W  
1/4  
S5 | S4  
1994

**59.10** The N 1/16 section corner of sections 4 and 5, monumented with a badly decayed iron post, 1 inch diameter, firmly set, flush with surface of ground, marked and witnessed as described in the field notes of the 1919 resurvey record.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

N 1/16  
S5 | S4  
1994

Deposit the remains of the 1 inch iron post, alongside the aluminum post.

Set a steel fence post, 5 ft. long, alongside the aluminum post.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL  
LINES, T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

N. 0° 28' W., beginning new measurement.

- 20.49** The corner of sections 4, 5, 32, and 33, on the north boundary of the township, hereinbefore described.

---

Dependent Resurvey of the Subdivision of Section 3,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

Reestablishment of the Survey Executed by D.G. Major in 1882,  
and the Resurvey Executed by R. Gentry in 1919

---

From true point for the S 1/16 section corner of sections 2 and 3.

S. 89° 56' W., on the E - W center line of the S 1/2 of section 3.

Over nearly level land.

- 20.125** The SE 1/16 section corner of section 3, monumented with an iron post, 1 inch diameter, firmly set, projecting 10 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.

Corner is located 20 links E of bulldozed road.

---

S. 89° 56' W., beginning new measurement.

- 19.96** The center S 1/16 section corner of section 3, monumented with an iron post, 1 inch diameter, firmly set, projecting 10 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.
- 

S. 89° 55' W., beginning new measurement.

- 20.145** The SW 1/16 section corner of section 3, monumented with an iron post, 1 inch diameter, filled with concrete, firmly set, projecting 10 inches above ground. The brass cap has been removed.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

SW 1/16 S3  
1994

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 3,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

Deposit the 1919 resurvey iron post alongside the aluminum post.

Corner is located 39 links W of N and S fence line.

N. 89° 55' W., beginning new measurement.

**20.03** The S 1/16 section corner of sections 3 and 4.

From the 1/4 section corner of sections 2 and 3.

S. 89° 57' W., on the E - W center line of section 3.

**19.97** Point for the center E 1/16 section corner of section 3, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

C ——— E 1/16 ——— C  
                  S3  
                  1994

**34.00** Lake Fork River, drains SE (scaled).

**39.94** The center 1/4 section corner of section 3, monumented with an iron post, 1 inch diameter, firmly set, projecting 6 inches above ground, marked and witnessed as described in the field notes of the 1919 resurvey record.

S. 89° 57' W., beginning new measurement.

**20.085** The center W 1/16 section corner of section 3, monumented with an iron post, 1 inch diameter, filled with concrete, firmly set, projecting 1 inch above ground. Upper portion with brass cap has been broken off and lying nearby.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, over a magnet, 24 inches in the ground, with magnet at base, with aluminum cap marked:

C ——— W 1/16 ——— C  
                  S3  
                  1994

Deposit the broken portions of the original iron post alongside the aluminum post.

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 3,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

Corner is located 3 links E of N and S fence line, and 3.75 chains S of E and W fence line.

N. 89° 58' W., beginning new measurement.

**20.17** The 1/4 section corner of sections 3 and 4.

Dependent Resurvey of the Subdivision of Section 4,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

Reestablishment of the Survey Executed by D.G. Major in 1882,  
and the Resurvey Executed by R. Gentry in 1919

From the S 1/16 section corner of sections 3 and 4.

S. 89° 54' W., on the E - W center line of the S 1/2 of section 4.

Over nearly level land.

**20.015** Point for the southeast 1/16 section corner of section 4, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

SE 1/16 S4  
1994

Corner is located 38 links W of N and S fence line, and 36 links E of a N and S fence line.

**40.03** Point for the center S 1/16 section corner of section 4, at proportionate distance, falls in center of N and S dirt road; there is no remaining evidence of the 1919 resurvey corner.

Drive a nail, 4 inches long, flush with surface of road.

from which

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears S. 39° 42' W., 39 links distance, with aluminum cap marked T3S R3W S4 RM 1994 25.7 FT. and an arrow pointing to the corner.

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 4,  
T. 3 S., R. 3 W., SALT LAKE MERIDIAN, UTAH

CHAINS

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears N. 61° 20' W., 53 1/2 links distance, with aluminum cap marked T3S R3W S4 RM 1994 35.2 FT. and an arrow pointing to the corner.

**60.045** Point for the SW 1/16 section corner of section 4, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner; not monumented.

**80.06** Point for the S 1/16 section corner of sections 4 and 5.

---

From the 1/4 section corner of sections 3 and 4.

S. 89° 53' W., on the E - W center line of section 4.

Over nearly level land.

**20.015** Point for the center E 1/16 section corner of section 4, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

$$\begin{array}{c} \text{C} \quad \frac{\text{E } 1/16}{\text{S4}} \quad \text{C} \\ 1994 \end{array}$$

Corner is located 14 links W of N and S fence line.

**40.03** Point for the center 1/4 section corner of section 4, at proportionate distance, falls in center of N and S road; there is no remaining evidence of the 1919 resurvey corner.

Drive a nail, 4 inches long, flush with surface of road.

from which

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears S. 7° 30' W., 144 links distance, with aluminum cap marked T3S R3W S4 RM 1994 95.0 FT. and an arrow pointing to the corner point.

An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears N. 20° 00' W., 57 1/2 links distance, with aluminum cap marked T3S R3W S4 RM 1994 37.9 FT. and an arrow pointing to the corner point.

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 4,  
T. 3 S., R. 3 W., SALT LAKE MERIDIAN, UTAH

## CHAINS

- 60.045** Point for the center W 1/16 section corner of section 4, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner, not monumented, .
- 80.06** The 1/4 section corner of sections 4 and 5.
- 
- From the N 1/16 section corner of sections 3 and 4.
- S. 89° 53' W., on the E - W center line of the N 1/2 of section 4.
- Over nearly level land.
- 20.02** The NE 1/16 section corner of section 4, monumented with an iron post, 1 inch diameter, filled with concrete, firmly set, projecting 2 inches above ground. Upper portion with brass cap has broken off and cannot be found.
- At the corner point
- Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:
- NE 1/16 S4  
1994
- Deposit the remaining portion of the original iron post alongside the aluminum post.
- Corner is located 32 1/2 links E of N and S fence line.
- 
- S. 89° 51' W., beginning new measurement.
- 20.015** Point for the center N 1/16 section corner of section 4, at proportionate distance, falls in center of a paved road, which bears N and S; there is no remaining evidence of the 1919 resurvey corner.
- Drive a nail, 4 inches long, flush with surface of road.
- from which
- An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears S. 39° 35' W., 74 links distance, with aluminum cap marked T3S R3W S4 RM 1994 48.8 FT. and an arrow pointing to the corner.
- An aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, for a reference monument, bears N. 41° W., 73 links distance, with aluminum cap marked T3S R3W S4 RM 1994 48.2 FT. and an arrow pointing to the corner.

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 4,  
T. 3 S., R. 3 W., SALT LAKE MERIDIAN, UTAH

**CHAINS****40.03**

Point for the NW 1/16 section corner of section 4, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner, not monumented.

**60.045**

The N 1/16 section corner of sections 4 and 5.

---

Dependent Resurvey of the Subdivision of Section 9,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

Reestablishment of the Survey Executed by D.G. Major in 1882,  
and the Resurvey Executed by R. Gentry in 1919

---

From the S 1/16 section corner of sections 9 and 10.

S. 89° 43' W., on the E - W center line of the S 1/2 of section 9.

Over nearly level land.

**19.93**

The southeast 1/16 section corner of section 9, monumented with an iron post, 1 inch diameter, firmly set, projecting 10 inches above ground, marked and witnessed as described in the resurvey of the subdivision of section 9 in 1919.

---

S. 89° 54' W., beginning new measurement.

**19.98**

The center S 1/16 section corner of section 9, monumented with an iron post, 1 inch diameter, firmly set, projecting 2 inches above ground, the upper portion of iron post with brass cap has been broken off and cannot be found.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

$$\begin{array}{ccc} & C & \\ S\ 1/16 & | & S9 \\ & C & \\ & 1994 & \end{array}$$

Deposit the broken original iron post, alongside the aluminum post.

---

S. 89° 50' W., beginning new measurement.

**19.96**

Point for the southwest 1/16 section corner of section 9, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 9,  
T. 3 S., R. 3 W., UTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

SW 1/16 S9  
1994

**39.92** The S 1/16 section corner of sections 8 and 9.

---

From the 1/4 section corner of sections 9 and 10.

S. 89° 55' W., on the E - W center line of section 9.

Over nearly level land.

**19.685** The center E 1/16 section corner of section 9, monumented with an iron post, 1 inch diameter, firmly set, projecting 1 inch above ground. Upper portion of iron post with brass cap has been broken off and was lying nearby.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

C ——— E 1/16 ——— C  
S9  
1994

Deposit the broken iron post alongside the aluminum post.

---

S. 89° 55' W., beginning new measurement.

**19.68** The center 1/4 section corner of section 9, monumented with an iron post, 1 inch diameter, firmly set, projecting 1 inch above ground, with the original sandstone 12x10x6 inches, marked C 1/4 on S face, and set by D.G. Major in 1882, alongside the iron post. The upper portion of the iron post has been broken off and could not be found.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

T3S R3W  
C 1/4 S9  
1994

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 9,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

Deposit the marked rock and broken iron post alongside the aluminum post.

Corner is located 25 links S of E and W fence line, and 26 1/2 links E of N and S fence line.

---

N. 89° 49' W., beginning new measurement.

- 20.08** Point for the center W 1/16 section corner of section 9, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

$$C \frac{W \ 1/16}{S9} C$$

1994

Corner is located 19 links W of N and S fence line.

- 40.16** The 1/4 section corner of sections 8 and 9.

---

From the N 1/16 section corner of sections 9 and 10.

S. 89° 46' W., on the E - W center line of the N 1/2 of section 9.

Over nearly level land.

- 19.84** The northeast 1/16 section corner of section 9, monumented with an iron post, 1 inch diameter, firmly set in swamp land, 6 inches below water. Upper portion of iron post with brass cap has been broken off and could not be found.

At the corner point

Set a steel fence post, 5 ft. long, over a magnet, 24 inches in the ground and alongside the broken iron post.

---

N. 89° 54' W., beginning new measurement.

- 19.99** The center N 1/16 section corner of section 9, monumented with a badly deteriorated iron post, 1 inch diameter, firmly set, with brass cap lying nearby.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 9,  
T. 3 S., R. 3 W., UTAH SPECIAL MERIDIAN, UTAH

CHAINS

C  
N 1/16 | S9  
C  
1994

Deposit the remains of original iron post alongside the aluminum post.

Corner is located 10 links W of old N and S fence line, and 19 links S of old E and W fence line.

N. 89° 58' W., beginning new measurement.

**19.96** Point for the northwest 1/16 section corner of section 9, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

NW 1/16 S9  
1994

Set a steel fence post, alongside the aluminum post.

Corner is located 43 1/2 links S of E and W fence line, and 78 links W of N and S fence line.

**39.92** The N 1/16 section corner of sections 9 and 10.

---

Dependent Resurvey of the Subdivision of Section 10,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

Reestablishment of the Survey Executed by D.G. Major in 1882,  
and the Resurvey Executed by R. Gentry in 1919

---

From the S 1/16 section corner of sections 10 and 11.

N. 89° 55' W., on the E - W center line of the S 1/2 of section 10.

Over nearly level land.

**20.03** The southeast 1/16 section corner of section 10, monumented with an iron post, 1 inch diameter, firmly set, buried 12 inches below surface of ground. Upper portion has been broken off and could not be found.

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 10,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

CHAINS

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

SE 1/16 S10  
1994

Deposit the iron post alongside the aluminum post.

Corner is located 28 links N of E and W fence line, and 17 links E of N and S fence line.

---

S. 89° 59' W., beginning new measurement.

20.03

The center S 1/16 section corner of section 10, monumented with an iron post, 1 inch diameter, lower portion firmly set, with upper portion bent over flush with surface of ground; with brass cap marked as described in the field notes of the 1919 resurvey record.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

C  
S 1/16 | S10  
C  
1994

Deposit the iron post alongside the aluminum post.

Set a 6 ft. steel fence post alongside the aluminum post.

Corner is located 31 links S of E and W fence line.

---

N. 89° 59' W., beginning new measurement.

20.03

The SW 1/16 section corner of section 10, monumented with an iron post, 1 inch diameter, firmly set but bent over in "L" shape, marked as described in the field notes of the 1919 resurvey record. The iron post is located in a swamp area where it is not practicable to remonument.

Set a steel fence post alongside the "L" shaped iron post.

Corner is located 37 links W of N and S fence line.

---

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 10,  
T. 3 S., R. 3 W., UTAH SPECIAL MERIDIAN, UTAH

CHAINS

N. 89° 54' W., beginning new measurement.

**20.105** The S 1/16 section corner of sections 9 and 10.

---

From the true point for the 1/4 section corner of sections 10 and 11.

N. 89° 58' W., on the E - W center line of section 10.

Over nearly level land.

**20.065** Point for the center E 1/16 section corner of section 10, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

$$\begin{array}{c} \text{C} \quad \frac{\text{E } 1/16}{\text{S10}} \quad \text{C} \\ 1994 \end{array}$$

Corner is located 3 links N of E and W fence line.

**40.13** Point for the center 1/4 section corner of section 10, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

$$\begin{array}{c} \text{T3S R3W} \\ \text{C } 1/4 \quad \text{S10} \\ 1994 \end{array}$$

Corner is located 62 links S of E and W fence line, and 52 links W of N and S fence line.

**60.195** Point for the center W 1/16 section corner of section 10, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

$$\begin{array}{c} \text{C} \quad \frac{\text{W } 1/16}{\text{S10}} \quad \text{C} \\ 1994 \end{array}$$

Corner is located 87 links W of N and S fence line, and 59 links S of E and W fence line.

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 10,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

## CHAINS

80.26

The 1/4 section corner of sections 9 and 10.

---

From the N 1/16 section corner of sections 10 and 11.

S. 89° 59' W., on the E - W center line of the N 1/2 of section 10.

Over nearly level land.

20.05

Point for the northeast 1/16 section corner of section 10, at proportionate distance; there is no remaining evidence of the 1919 resurvey corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

NE 1/16 S10  
1994

40.10

The center N 1/16 section corner of section 10, monumented with an iron post, 1 inch diameter, firmly set, projecting 1 inch above ground. The upper portion with brass cap has been broken off and could not be found.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

C  
N 1/16 | S10  
C  
1994

Deposit broken portion of iron post alongside the aluminum post.

---

S. 89° 53' W., beginning new measurement.

20.045

The northwest 1/16 section corner of section 10, monumented with an iron post, 1 inch diameter, firmly set, with top portion, 12 inches long, bent over flush with surface of ground.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet at base, with aluminum cap marked:

NW 1/16 S10  
1994

DEPENDENT RESURVEY OF THE SUBDIVISION OF SECTION 10,  
T. 3 S., R. 3 W., UTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

Deposit the iron post alongside the aluminum post.

---

N. 89° 52' W., beginning new measurement.

**20.135** The N 1/16 section corner of sections 9 and 10.

---

Survey of a Portion of the Subdivision of Section 3,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

From the E 1/16 section corner of sections 3 and 10.

N. 0° 38' W., on the N - S center line of the SE 1/4 of section 3.

**19.89** The SE 1/16 section corner of section 3.

---

N. 0° 01' W., beginning new measurement.

**19.74** The center E 1/16 section corner of section 3.

---

From the 1/4 section corner of sections 3 and 10.

N. 0° 24' W., on the N - S center line of section 3.

**19.77** The center S 1/16 section corner of section 3.

---

N. 0°03' W., beginning new measurement.

**19.745** The center 1/4 section corner of section 3.

---

From the W 1/16 section corner of sections 3 and 10.

N. 0° 28' W., on N - S center line of the SW 1/4 of section 3.

**19.72** The SW 1/16 section corner of section 3.

---

N. 0°07' E., beginning new measurement.

**19.755** The center W 1/16 section corner of section 3.

---

SURVEY OF A PORTION OF THE SUBDIVISION OF SECTION 4,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

Survey of a Portion of the Subdivision of Section 4,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

From the E 1/16 section corner of sections 4 and 9.

N. 0°18' W., on the N - S center line of the E 1/2 of section 4.

**19.725** The SE 1/16 section corner of section 4.

---

N. 0°19' W., beginning new measurement.

**19.725** The center E 1/16 section corner of section 4.

---

N. 0°19' W., beginning new measurement.

**19.735** The NE 1/16 section corner of section 4.

---

N. 0°19' W., beginning new measurement.

**20.305** The E 1/16 section corner of sections 4 and 33, on the north boundary of the township, hereinbefore described.

---

From the 1/4 section corner of sections 4 and 9.

N. 0°19' W., on a portion of the N - S center line of section 4.

**19.715** The center S 1/16 section corner of section 4.

---

N. 0°19' W., beginning new measurement.

**19.715** The center 1/4 section corner of section 4.

---

N. 0°19' W., beginning new measurement.

**19.725** The center N 1/16 section corner of section 4.

---

N. 0°22' W., beginning new measurement.

SURVEY OF A PORTION OF THE SUBDIVISION OF SECTION 4,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS****20.37**

The 1/4 section corner of sections 4 and 33 on the north boundary of the township, hereinbefore described.

---

From the W 1/16 section corner of sections 4 and 9.

N. 0°20' W., on the N-S center line of the W 1/2 of section 4.

**19.71**

Point for the SW 1/16 section corner of section 4; not monumented.

---

N. 0°19' W., beginning new measurement.

**19.71**

Point for the center W 1/16 section corner of section 4; not monumented.

---

N. 0°20' W., beginning new measurement.

**19.71**

Point for the NW 1/16 section corner of section 4; not monumented.

---

N. 0°25' W., beginning new measurement.

**20.43**

Point for the W 1/16 section corner of sections 4 and 33, hereinbefore described; not monumented.

---

Survey of a Portion of the Subdivision of Section 9,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

From the E 1/16 section corner of sections 9 and 16.

N. 0°31' W., on the N-S center line of the E 1/2 of section 9.

**19.745**

The SE 1/16 section corner of section 9.

---

N. 0°01' E., beginning new measurement.

**19.855**

The center E 1/16 section corner of section 9.

---

N. 1°03' W., beginning new measurement.

**19.75**

The NE 1/16 section corner of section 9.

---

SURVEY OF A PORTION OF THE SUBDIVISION OF SECTION 9,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

- N. 1°03' W., beginning new measurement.
- 19.85** The E 1/16 section corner of sections 4 and 9.
- 
- From the true point for the 1/4 section corner of sections 9 and 16.
- N. 0°19' W., on the N - S center line of section 9.
- 19.88** The center S 1/16 section corner of section 9.
- 
- N. 0°53' E., beginning new measurement.
- 19.865** The center 1/4 section corner of section 9.
- 
- N. 1°57' W., beginning new measurement.
- 19.82** The center N 1/16 section corner of section 9.
- 
- N. 1°07' W., beginning new measurement.
- 19.79** The 1/4 section corner of sections 4 and 9.
- 
- From the W 1/16 section corner of sections 9 and 16.
- N. 0°04' W., on the N - S center line of the W 1/2 of section 9.
- 19.99** The SW 1/16 section corner of section 9.
- 
- N. 0°32' E., beginning new measurement.
- 19.985** The center W 1/16 section corner of section 9.
- 
- N. 1°36' W., beginning new measurement.
- 19.76** The NW 1/16 section corner of section 9.
- 
- N. 1°16' W., beginning new measurement.
- 19.75** True point for the W 1/16 section corner of sections 4 and 9.
-

SURVEY OF A PORTION OF THE SUBDIVISION OF SECTION 10,  
T. 3 S., R. 3 W., UTAH SPECIAL MERIDIAN, UTAH

**CHAINS**

Survey of a Portion of the Subdivision of Section 10,  
T. 3 S., R. 3 W., Uintah Special Meridian, Utah

---

From the E 1/16 section corner of sections 10 and 15.

N. 0°13' W., on a portion of the N - S center line of the E 1/2 of section 10.

**19.93** The SE 1/16 section corner of section 10.

---

N. 0°36' W., beginning new measurement.

**19.80** The center E 1/16 section corner of section 10.

---

N. 0°28' W., beginning new measurement.

**19.81** The NE 1/16 section corner of section 10

---

N. 0°26' W., beginning new measurement.

**19.64** The E 1/16 section corner of sections 3 and 10.

---

From the 1/4 section corner of sections 10 and 15.

N. 0°18' W., on the N - S center line of section 10.

**19.86** The center S 1/16 section corner of section 10.

---

N. 0°42' W., beginning new measurement.

**19.815** The center 1/4 section corner of section 10.

---

N. 0°26' W., beginning new measurement.

**19.795** The center N 1/16 section corner or section 10.

---

N. 0°31' W., beginning new measurement.

**19.75** The 1/4 section corner of sections 3 and 10.

---

SURVEY OF A PORTION OF THE SUBDIVISION OF SECTION 10,  
T. 3 S., R. 3 W., UINTAH SPECIAL MERIDIAN, UTAH

*CHAINS*

From the W 1/16 section corner of sections 10 and 15.

N. 0°24' W., on the N - S center line of the W 1/2 of section 10.

**19.81** The SW 1/16 section corner of section 10.

---

N. 0°49' W., beginning new measurement.

**19.82** The center W 1/16 section corner of section 10.

---

N. 0°22' W., beginning new measurement.

**19.75** The NW 1/16 section corner of section 10.

---

N. 0°39' W., beginning new measurement.

**19.82** The W 1/16 section corner of sections 3 and 10.

---

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**FIELD ASSISTANTS**

---

Name	Capacity
Steven Oatman	Survey Technician
Ryan Snow	Survey Aid

## CERTIFICATE OF SURVEY

I, *Jerry L. Thomas, Cadastral Surveyor*, hereby certify upon honor that, in pursuance of special instructions bearing the date of the *20th day of May, 1994*, I have *dependently resurveyed portions of the north boundary, and subdivisional lines, and dependently resurveyed a portion of the subdivision of sections 3, 4, 9, and 10, (originally surveyed by the Three Mile Method), and surveyed the subdivision of sections 3, 4, 9, and 10, in Township 3 South, Range 3 West,*

of the *Uintah Special Meridian*, in the State of *Utah*, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

Dec. 23, 1998

Date

Jerry L. Thomas

(Cadastral Surveyor)

\_\_\_\_\_

Date

\_\_\_\_\_

(Cadastral Surveyor)

## CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT  
Salt Lake City, Utah

The foregoing field notes of the *dependent resurvey of portions of the north boundary and subdivisional lines, and the dependent resurvey of a portion of the subdivision of sections 3, 4, 9, and 10, (originally surveyed by the Three Mile Method) and the survey of the subdivision of sections 3, 4, 9, and 10, in Township 3 South, Range 3 West, Uintah Special Meridian, Utah,*

executed by *Jerry L. Thomas, Cadastral Surveyor*

having been critically examined and found correct, are hereby approved.

Jan. 11, 1999

Date

Daniel W. Wells

(Chief Cadastral Surveyor for Utah Office)