

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

ORIGINAL

FIELD NOTES

OF

THE DEPENDENT RESURVEY

OF

A PORTION OF THE EAST BOUNDARY,

A PORTION OF THE NORTH BOUNDARY,

A PORTION OF THE SUBDIVISIONAL LINES,

AND

THE SUBDIVISION OF SECTIONS 1 AND 25,

IN

**TOWNSHIP 9 SOUTH, RANGE 4 WEST,**

OF THE SALT LAKE MERIDIAN  
IN THE STATE OF UTAH

EXECUTED BY

**Matthew J. Kurchinski**  
**Cadastral Surveyor**

Under Special Instructions dated and approved **September 20, 2013**, and Supplemental Special Instructions dated and approved **May 2, 2014**, which provided for the surveys included under Group No. **1241**, and Assignment Instructions dated **September 20, 2013**.

Survey Commenced, **September 23, 2013**  
Survey Completed, **June 5, 2014**

# INDEX DIAGRAM

TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

6	5	4	3	2	10 16 1 9 16
7	8	9	10	11	14 12 8 14
18	17	16	15	14	14 13 6 13
19	20	21	22	23	12 24 5 12
30	29	28	27	26	11 25 3 11
31	32	33	34	35	36

The Subdivision of section 1.....17  
 The Subdivision of section 25.....18

## TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

The following field notes describe the dependent resurvey of a portion of the east boundary, a portion of the north boundary, and a portion of the subdivisional lines, and the subdivision of sections 1 and 25, in T. 9 S., R. 4 W., Salt Lake Meridian, Utah.

## HISTORY OF SURVEYS

Surveyed by		Retr. or Resurveyed by	
<b>SOUTH BOUNDARY</b>			
Portion	A.D. Ferron	1871	
Portion	J. Gorlinski	1874	J. Gorlinski 1874
Portion	H.W. Miller & I. Hayes	1915	H.W. Miller & I. Hayes 1915
Portion			G.B. Hatch 1966
<b>EAST BOUNDARY</b>			
Portion	A.D. Ferron	1871	
Portion	H.W. Miller & I. Hayes	1915	H.W. Miller & I. Hayes 1915
Portion			J.C. Thoma 1919
<b>WEST BOUNDARY</b>			
Portion	A.D. Ferron	1871	
All	H.W. Miller & I. Hayes	1915	H.W. Miller & I. Hayes 1915
<b>NORTH BOUNDARY</b>			
All	A.D. Ferron	1871	
All			R. Gentry 1939
<b>SUBDIVISION</b>			
Portion	A.D. Ferron	1871	
Portion	H.W. Miller & I. Hayes	1915	H.W. Miller & I. Hayes 1915

## PRIVATE SURVEYS

A survey described as the "AMENDED DEPENDENT RESURVEY AND SUBDIVISION OF SECTION 15" was made by Oak Hills Surveying, signed and stamped by Francis D. Eickbush, Utah Registered Land Surveyor No. 317443, on June 27, 2005, and recorded at the Tooele County Recorder's Office under Serial No. 2005-0029-01.

## TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

The survey was executed in accordance with the specifications set forth in the Manual of Surveying Instructions, 2009, the Special Instructions for Group No. 1241, dated September 20, 2014, and the Supplemental Special Instructions dated May 2, 2014.

The direction of each line is with reference to the true meridian, determined by Global Positioning System (GPS) observations utilizing Real-Time Kinematic (RTK) techniques throughout the survey. The positional accuracy of this survey complies with the *Standards for the Positional Accuracy of Cadastral Surveys When Using Global Navigation Satellite Systems (GNSS)*, dated February 23, 2009. Trimble model R8-3 GPS receivers were used for field collection. Cadastral Automated Plat Drafting (CAPD) software was the primary software utilized for project calculations. All bearings are mean bearings. The distances are reported as horizontal measurement in chains. All lines not forming a closure were measured twice to preclude blunder.

Preliminary to the resurvey, the lines of the prior surveys were retraced and a search was made for all corners and other calls of record. Identified corners were remonumented in their original positions. Lost corners were reestablished and remonumented at proportionate positions based on the official record. The retracement data was thoroughly verified and only the true line field notes are given herein.

During the execution of this survey, fuels reduction activities ("bullhogging") were taking place within the sections resurveyed.

The bearing trees described with the common name "cedar" in previous records are described as "juniper" within these field notes.

Geodetic control was derived from GPS static observations, post processed by National Geodetic Survey, Online Positioning User Service (OPUS), utilizing Continuously Operating Reference Stations (CORS): DL7737 P113 KNOLLSWESTUT2006 CORS ARP, DH7098 P086 KENNECOTT1UT2005 CORS ARP, AJ6822 SLCU SALT LAKE CITY CORS ARP, and DH3864 P105 DELTAMUNI\_UT2004 CORPS ARP.

The geographic position of the corner of sections 25, 26, 35, and 36, Township 9 South, Range 4 West, as determined by direct RTK methods from the geodetic control is as follows:

Latitude: **39°59'53.273" N.**,  
 Longitude: **112°15'01.115" W.**, N.A.D. 83 (2011) (EPOCH: 2010.00)  
 Network Accuracy = 0.200 meter at 95% confidence.

The geographic position of the corner of sections 1 and 36 only, Townships 8 and 9 South, Range 4 West, as determined by direct RTK methods from the geodetic control is as follows:

Latitude: **40°04'15.809" N.**,  
 Longitude: **112°13'53.684" W.**, N.A.D. 83 (2011) (EPOCH: 2010.00)  
 Network Accuracy = 0.200 meter at 95% confidence.

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

---

Dependent Resurvey of a Portion of the East Boundary,  
T. 9 S., R. 4 W., Salt Lake Meridian, Utah

---

Reestablishment of the Surveys Executed by A.D. Ferron in 1871  
and H.W. Miller & I. Hayes in 1915;  
and the Dependent Resurvey by J.C. Thoma in 1919

---

Beginning at the corner of sections 25 and 36 only, on the east boundary of the township, monumented with an iron post, 3 inches diameter, firmly set, projecting 14 inches above the ground, in a partially scattered mound of stone, with brass cap marked as described in the official record of the 1915 survey, from which the 1915 bearing trees

A dead and standing mahogany, 7 inches diameter, bears S. 10° W., 24.6 links distance, with faint, illegible scribe marks on an open blaze. (Record, S. 14° W., 23 links)

A juniper, 23 inches diameter, bears N. 45 3/4° W., 28.3 links distance, marked T9SR4WS25BT on an open blaze. (Record, N. 50° W., 27 links)

Rebuild supporting mound of stone, 4 feet base, to brass cap.

Corner is located on a rocky, steep, west-facing slope; pinon, mahogany, juniper, and sagebrush.

N. 0°07.7' E., between sections 25 and 31.

- 3.428** The corner of sections 30 and 31 only, T. 9 S., R. 3 W., monumented with an iron post, 2 inches diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1919 resurvey, from which the remaining 1919 bearing trees

Root crown of a dead and fallen spruce, 11 inches diameter, bears N. 64 1/2° E., 41.7 links distance, with scribe marks R3W visible on a partially-healed blaze. (Record, N. 56° E., 41 links)

A dead and standing pinon, 15 inches diameter, bears S. 86 1/4° E., 27.9 links distance, with illegible scribe marks on a partially-healed blaze. (Record, S. 10° E., 28 links)

Raise a supporting mound of stone, 2 feet base, to brass cap.

---

N. 1°14.7' E., between sections 25 and 30.

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

- 34.300** Two-track road, bears N. 80° W. and S. 80° E., in bottom of canyon, drains NW.
- 36.662** Point for the 1/4 section corner of section 25 only, at proportionate distance; there is no remaining evidence of the 1915 iron post.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 8 inches in the ground to bedrock, in a mound of stone, 4 feet base, to aluminum cap marked

T9S  
R4W | R3W  
1/4  
S25  
2014

From which

A pinon, 5 inches diameter, bears S. 35 1/4° W., 37.0 links distance, marked X BT.

A pinon, 12 inches diameter, bears N. 37 1/4° W., 26.7 links distance, marked 1/4 S25 BT.

Deposit a magnet in a plastic case beneath the aluminum post.

Corner is located on a rocky, steep, southwest-facing slope; dense pinon, juniper, and mahogany.

- 40.725** The 1/4 section corner of section 30 only, T. 9 S., R. 3 W., monumented with an iron post, 1 inch diameter, firmly set, projecting 14 inches above the ground, with brass cap marked as described in the official record of the 1919 resurvey, with a scattered mound of stone along south side.

There is no remaining evidence of the 1919 bearing tree.

Rebuild mound of stone to 2 feet base, 1 1/2 feet high, south of the iron post.

Corner is located on a rocky, steep, southwest-facing slope; thick juniper and pinon.

---

N. 1°22.7' W., beginning new measurement.

- 36.480** Point for the corner of sections 24 and 25 only, at proportionate distance. The original 1915 iron post, concrete filled, 3 inches diameter, 36 inches long, was found lying loose on the ground, approximately 30 links northwesterly (downhill), with brass cap marked as described in the official record of the 1915 survey.

Reset the 1915 iron post, 4 inches in the ground to solid rock, in

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

a mound of stone, 5 1/2 feet base, to top of brass cap.

Deposit a magnet in a plastic case beneath the iron post.

Add marks 2014 to cap.

From which the new accessories

An "X", 4 inches tall, and "BO", 2 inches tall, chiseled into a blue limestone outcrop, 4 x 3 feet, projecting 2 feet, bears S. 48° W., 31.9 links distance.

A pinon, 12 inches diameter, bears N. 25 3/4° W., 51.6 links distance, marked T9S R4W S24 BT.

Corner is located on a steep, rocky, north-facing slope; dense pinon.

---

N. 1°22.7' W., between sections 24 and 30.

- 3.718** The corner of sections 19 and 30 only, T. 9 S., R. 3 W., monumented with an iron post, 2 inches diameter, firmly set, projecting 8 inches above the ground, with brass cap marked as described in the official record of the 1919 resurvey, with a scattered mound of stone along east side.

Rebuild mound of stone to 2 1/2 feet base, 2 feet high, east of the iron post.

---

N. 0°00.8' E., between sections 19 and 24.

- 36.456** The 1/4 section corner of section 24 only, monumented with an iron post, 1 inch diameter, loosely set, projecting 24 inches above the ground, with brass cap marked as described in the official record of the 1915 survey, with a scattered mound of stone downhill from the corner.

Rebuild supporting mound of stone to 2 1/2 feet base, to brass cap.

Set a steel fence post east of the iron post.

Corner is located on a rocky, steep, west-facing slope; pinon and juniper.

---

N. 0°52.7' E., beginning new measurement.

- 3.383** The 1/4 section corner of section 19 only, T. 9 S., R. 3 W., monumented with an iron post, 1 inch diameter, firmly set, projecting 18 inches above the ground, with brass cap marked as described in the official record of the 1919 resurvey. There is no remaining evidence of the 1919 supporting mound of stone or

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

accessory mound of stone.

Raise supporting mound of stone, 3 feet base, to brass cap.

Set a steel fence post alongside the iron post.

Corner is located on a steep, north-facing slope, with limestone outcrops; pinon and juniper; scattered sagebrush and grass.

N. 0°07.0' W., beginning new measurement.

- 36.985** The corner of sections 13 and 24 only, monumented with an iron post, 3 inches diameter, firmly set, projecting 12 inches above the ground, in a small collar of stone, with brass cap marked as described in the official record of the 1915 survey, with a mound of stone, 2 feet base, 1 foot high, along west side.

Set a steel fence post along west side of the iron post.

N. 0°03.0' W., between sections 13 and 19.

- 3.053** The corner of sections 18 and 19 only, T. 9 S., R. 3 W., monumented with an iron post, 2 inches diameter, firmly set, projecting 16 inches above the ground, in an embedded mound of stone, 2 1/2 feet base, with brass cap marked as described in the official record of the 1919 resurvey, with a mound of stone, 2 feet base, 1 foot high, along east side.

Set a steel fence post along east side of the iron post.

N. 0°03.6' E., between sections 13 and 18.

- 39.035** The 1/4 section corner of section 13 only, determined at record bearing and distance from the 1915 bearing tree

A pinon, 11 inches diameter, bears S. 13° W., 26.0 links distance, with illegible scribe marks on a partially healed blaze.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 27 inches in the ground, with aluminum cap marked

```

      T9S
      R4W | R3W
1/4 S13 |
          |
          2013
  
```

Deposit a magnet in a plastic case beneath the aluminum post.

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

Set a steel fence post along west side of the aluminum post.

Find a scattered mound of stone near the corner point. Rebuild mound of stone to 2 feet base, 1 1/2 feet high, west of the aluminum post.

Corner is located 17 links west of the center of a wash, 8 feet wide, drains N. 14° W.

---

N. 0°26.0' W., beginning new measurement.

- 1.031 The 1/4 section corner of section 18 only, T. 9 S., R. 3 W., monumented with an iron post, 1 inch diameter, firmly set, projecting 22 inches above the ground, in a scattered mound of stone, with brass cap marked as described in the official record of the 1919 resurvey.

Rebuild supporting mound of stone to 3 1/2 feet base, to brass cap.

Set a steel fence post south of the iron post.

---

N. 0°07.8' E., beginning new measurement.

- 38.961 The corner of sections 12 and 13 only, monumented with an iron post, 3 inches diameter, firmly set, projecting 10 inches above the ground, with brass cap marked

	T9S
	R4W R3W
S12	
S13	
	1915

The original 1871 sandstone, firmly set, projecting 16x10x6 inches above the ground, marked with 4 notches on south and 2 notches on north edges is along west side of iron post; a mound of stone, 2 feet base, 1 1/2 feet high, is along west side of the marked stone.

Set a steel fence post south of the iron post.

---

N. 0°14.3' W., between sections 12 and 18.

- 1.012 The corner of sections 7 and 18 only, T. 9 S., R. 3 W., monumented with an iron post, 2 inches diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1919 resurvey, with a scattered mound of stone along east side, and with a perforated PVC pipe, 4 inches

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

diameter, projecting 4 feet above a mound of stone, 2 feet base, 1 foot high, along south side, from which the remains of the 1919 bearing tree

A cut pinon stump, 12 inches diameter, 3 feet high, bears N.  $35\frac{1}{2}^{\circ}$  E., 150.4 links distance, with cut up pieces of the trunk lying nearby, with scribed marks T9S R3W BT visible on pieces and stump when together. (Record, N.  $36^{\circ}$  E., 151 links)

Rebuild mound of stone to 3 feet base, 2 feet high, east of the iron post.

Set a steel fence post along north side of the iron post.

---

N.  $0^{\circ}19.0'$  W., between sections 7 and 12.

38.772 The 1/4 section corner of section 12 only, monumented with an iron post, 1 inch diameter, firmly set, projecting 12 inches above the ground, in a small collar of stone, with brass cap marked as described in the official record of the 1919 resurvey, with a light gauge steel fence post along north side, from which the 1919 bearing trees

A pinon, 11 inches diameter, bears S.  $55\frac{1}{4}^{\circ}$  W., 44.1 links distance, with illegible scribe marks on a partially healed blaze. (Record, S.  $54^{\circ}$  W., 43 links)

A dead and standing pinon, 8 inches diameter, bears N.  $23\frac{3}{4}^{\circ}$  W., 115.7 links distance, with illegible scribe marks on a partially healed blaze. (Record, N.  $24^{\circ}$  W., 115 links)

---

N.  $0^{\circ}12.9'$  E., beginning new measurement.

1.018 The 1/4 section corner of section 7 only, T. 9 S., R. 3 W., monumented with an iron post, 1 inch diameter, firmly set, projecting 14 inches above the ground, in a collar of stone, with brass cap marked as described in the official record of the 1919 resurvey, from which the 1919 bearing trees

A stump hole, bears N.  $36\frac{3}{4}^{\circ}$  E., 149.3 links distance, with a dead and down pinon alongside, 12 inches diameter, with illegible scribe marks on a partially healed blaze. (Record, N.  $36^{\circ}$  E., 151 links)

A juniper, 6 inches diameter, bears N.  $84^{\circ}$  E., 100.1 links distance, with illegible scribe marks on a partially healed blaze. (Record, 101 links)

Set a steel fence post north of the iron post.

---

N.  $0^{\circ}16.0'$  W., beginning new measurement.

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

- 38.724** The corner of sections 1 and 12 only, monumented with an iron post, 2 inches diameter, firmly set, projecting 9 inches above the ground, with brass cap marked as described in the official record of the 1919 resurvey, with the original 1871 limestone, firmly set, projecting 9x6x4 inches above the ground, along west side, and a light gauge steel fence post along north side, from which the remaining 1919 bearing tree

A juniper, 8 inches diameter, bears S. 62° W., 59.5 links distance, with illegible scribe marks on a partially healed blaze. (Record, 61 links)

---

N. 0°06.4' E., between sections 1 and 7.

- 1.013** The corner of sections 6 and 7 only, T. 9 S., R. 3 W., monumented with an iron post, 2 inches diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1919 resurvey, with a mound of stone, 2 feet base, 1 1/2 feet high, along east side, and a light gauge steel fence post along north side.
- 

N. 0°26.4' W., between sections 1 and 6.

- 38.842** The 1/4 section corner of section 1 only, monumented with an iron post, 1 inch diameter, firmly set, projecting 6 inches above a collar of stone, with brass cap marked as described in the official record of the 1919 resurvey, with a mound of stone, 2 1/2 feet base, 1 foot high, along west side, and a steel fence post along south side.

Corner is located on the northeast side of a small wash, drains northwesterly; dense sagebrush and scattered juniper.

---

N. 0°03.9' E., beginning new measurement.

- 1.031** The 1/4 section corner of section 6 only, T. 9 S., R. 3 W., monumented with an iron post, 1 inch diameter, firmly set, projecting 14 inches above an embedded mound of stone, with brass cap marked as described in the official record of the 1919 resurvey, with a mound of stone, 2 1/2 feet base, 1 1/2 feet high, along east side, and a light gauge steel fence post along north side.

Raise a supporting mound of stone, 3 feet base, to brass cap.

Corner is located in dense sagebrush and scattered juniper.

---

N. 0°25.4' W., beginning new measurement.

- 38.849** The corner of Townships 8 and 9 South, Range 4 West, monumented

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

with an iron post, 3 inches diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1913 survey of the south boundary of T. 8 S., R. 3 W.; with an embedded mound of stone, 3 feet base, 1 foot high, along west side.

Corner is located at a corner of fences extending north and west; level ground; dense sagebrush.

---

N.  $0^{\circ}01.2'$  E., between sections 6, T. 9 S., R 3 W., and section 36 T. 8 S., R 4 W.

- 4.207 The closing corner of Townships 8 and 9 South, Range 3 West, monumented with an iron post, 3 inches diameter, firmly set, projecting 21 inches above the ground, in a mound of stone, 4 feet base, to brass cap marked as described in the official record of the 1913 survey of the south boundary of T. 8 S., R. 3 W.

Corner is located in an abandoned fence, bears north and south; level ground; dense sagebrush.

---

Dependent Resurvey of a Portion of the North Boundary,  
T. 9 S., R. 4 W., Salt Lake Meridian, Utah

---

Reestablishment of the Survey Executed by A.D. Ferron in 1871,  
and the Dependent Resurvey by R. Gentry in 1939

---

From the corner of Townships 8 and 9 South, Range 4 West, hereinbefore described.

S.  $89^{\circ}47.8'$  W., between sections 1 and 36.

- 39.922 The 1/4 section corner of sections 1 and 36, monumented with an iron post, 1 inch diameter, firmly set, projecting 5 inches above the ground, with brass cap marked as described in the official record of the 1939 resurvey, with an embedded mound of stone, 2 feet base, along north side.

Corner is located in an abandoned fence, bears east and west; level ground; grass and dense sagebrush.

---

S.  $89^{\circ}44.9'$  W., beginning new measurement.

- 40.150 The corner of sections 1, 2, 35, and 36, monumented with an iron post, 2 inches diameter, firmly set, projecting 2 inches above the ground, with brass cap marked as described in the official record of the 1939 resurvey.

Corner is located approximately 23 links north of a dirt road, bears northeast and southwest; level ground; grass and dense

DEPENDENT RESURVEY OF A PORTION OF THE NORTH,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

sagebrush.

From this corner, a corner of fences extending south and west,  
bears S. 33°18.3' W., 6.5 links distance.

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 9 S., R. 4 W., Salt Lake Meridian, Utah

Reestablishment of the Surveys Executed by A.D. Ferron in 1871  
and H.W. Miller & I. Hayes in 1915, and the Resurveys Executed by  
H.W. Miller & I. Hayes in 1915

From the corner of sections 25 and 36 only, on the east boundary  
of the township, hereinbefore described.

S. 89°57.4' W., between sections 25 and 36.

- 40.459 The 1/4 section corner of sections 25 and 36, monumented with an  
iron post, 1 inch diameter, firmly set, projecting 12 inches above  
the ground, with brass cap marked as described in the official  
record of the 1915 survey, with a mound of stone, 2 feet base, 1  
1/2 feet high, along north side.

Set a steel fence post east of the iron post.

Corner is located on a gentle west slope; dense juniper, pinon,  
and sagebrush.

S. 89°50.1' W., beginning new measurement.

- 40.028 The corner of sections 25, 26, 35, and 36, monumented with an iron  
post, 2 inches diameter, firmly set, projecting 12 inches above  
the ground, in an embedded mound of stone, with brass cap marked  
as described in the official record of the 1915 survey, with a  
scattered mound of stone along west side, and two fiberglass rods,  
projecting 3 feet, alongside.

Rebuild supporting mound of stone to 2 1/2 feet base, to brass  
cap.

Rebuild accessory mound of stone to 3 feet base, 1 1/2 feet high,  
west of the iron post.

Set a steel fence post southeast of the iron post.

N. 0°05.4' E., between sections 25 and 26.

- 40.438 The 1/4 section corner of sections 25 and 26, monumented with an  
iron post, 1 inch diameter, firmly set, projecting 12 inches above  
the ground, in a scattered mound of stone, with brass cap marked

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

as described in the official record of the 1915 survey.

Rebuild supporting mound of stone to 2 feet base, to brass cap.

Rebuild accessory mound of stone to 2 feet base, 1 foot high, west of the iron post.

Set a steel fence post south of the iron post.

Corner is located on level ground, in a dense group of juniper trees, with dense sagebrush and grass.

N. 0°04.1' W., beginning new measurement.

- 40.371** The corner of sections 23, 24, 25, and 26, monumented with an iron post, 2 inches diameter, firmly set, projecting 10 inches above the ground, with brass cap marked as described in the official record of the 1915 survey, with the original 1871 limestone, firmly set, projecting 8x6x5 inches, with 2 notches on south edge, along south side, and a scattered mound of stone along west side.

Rebuild mound of stone to 2 1/2 feet base, 1 1/2 feet high, along west side of the iron post.

Set a steel fence post east of the iron post.

Corner is located on level ground, in dense juniper and scattered pinion trees, with grass, and approximately 33 links east of a two-track road, bears South and N. 20° E.

From the corner of sections 24 and 25 only, on the east boundary of the township, hereinbefore described.

N. 89°55.6' W., between sections 24 and 25.

- 39.494** The 1/4 section corner of sections 24 and 25, monumented with an iron post, 1 inch diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1915 survey, with a mound of stone, 2 1/2 feet base, 2 feet high, along north side.

Build a collar of stone around the iron post.

Set a steel fence post east of the iron post.

Corner is located on level, rocky ground; juniper and pinon.

N. 89°59.8' W., beginning new measurement.

- 40.974** The corner of sections 23, 24, 25, and 26.

N. 0°06.9' W., between sections 23 and 24.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

- 40.258** The 1/4 section corner of sections 23 and 24, monumented with an iron post, 1 inch diameter, firmly set, projecting 10 inches above the ground, with brass cap marked as described in the official record of the 1915 survey. There is no remaining evidence of the 1915 accessory mound of stone.

Set a steel fence post alongside the iron post.

Corner is located on level ground, with scattered juniper and dense sagebrush, and 39 links east of a two-track road, 9 feet wide, bears N. 45° E. and S. 45° W.

---

N. 0°06.0' W., beginning new measurement.

- 40.223** The corner of sections 13, 14, 23, and 24, monumented with an iron post, 2 inches diameter, firmly set, projecting 9 inches above the ground, with brass cap marked as described in the official record of the 1915 survey, with the original 1871 limestone, firmly set, projecting 12x8x4 inches, with 3 notches on south and 1 notch on east edges, along east side, and a mound of stone, 2 1/2 feet base, 1 1/2 feet high, along west side.

Set a steel fence post north of the iron post.

---

From the corner of sections 13 and 24 only, on the east boundary of the township, hereinbefore described.

S. 89°57.3' W., between sections 13 and 24.

- 40.544** The 1/4 section corner of sections 13 and 24, monumented with an iron post, 1 inch diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1915 survey, from which the remains of the remaining 1915 bearing tree

A cut pinon stump, 9 inches diameter, 10 inches high, bears N. 52° W., 40.4 links distance, with lower portion of an open blaze but no marks visible. (Record, N. 52 1/2° W., 41 links)

Set a steel fence post east of the iron post.

Corner is located on a gentle west-facing slope; dense juniper, pinon, and sagebrush. Corner is also in an old burn and tree cutting area.

---

N. 89°57.9' W., beginning new measurement.

- 39.951** The corner of sections 13, 14, 23, and 24.
-

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

N. 0°14.0' W., between sections 13 and 14.

- 40.160 The 1/4 section corner of sections 13 and 14, monumented with an iron post, 1 inch diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1915 survey, with the original 1871 limestone, 16x6 x6 inches, lying loose alongside, marked 1/4 on a face. (Record, 15x10x8 inches) There is no remaining evidence of pits or mound of earth.

Set a steel fence post west of the iron post.

Corner is located on level ground; dense sagebrush and grass.

---

N. 0°06.3' W., beginning new measurement.

- 40.339 The corner of sections 11, 12, 13, and 14, monumented with an iron post, 2 inches diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1915 survey, with the original 1871 limestone, 12x6 x4 inches (Record, 16x8x8 inches), lying loose alongside, with 3 notches remaining (fourth broken off) on one edge, 1 notch on another edge, with a mound of stone, 2 1/2 feet base, 1 foot high, along west side, and an aluminum U-channel fence post with Forest Service decal along east side.

---

From the corner of sections 12 and 13 only, on the east boundary of the township, hereinbefore described.

S. 88°44.6' W., between sections 12 and 13.

- 40.658 The 1/4 section corner of sections 12 and 13, monumented with an iron post, 1 inch diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the official record of the 1915 survey, with a quartzite stone, firmly set, projecting 6x6x6 inches above the ground along south side, and an orange L-angle iron fence post along north side.

---

S. 89°00.6' W., beginning new measurement.

- 40.191 The corner of sections 11, 12, 13, and 14.

---

N. 0°01.6' W., between sections 11 and 12.

- 40.011 The 1/4 section corner of sections 11 and 12, monumented with a limestone, 11x8x5 inches (Record, 14x10x6 inches), loosely set, projecting 9 inches above the ground, marked 1/4 on a face, with an L-angle iron fence post along north side.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 27

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

inches in the ground, with aluminum cap marked

T9S R4W  
1/4  
S11 | S12  
2013

Deposit a magnet in a plastic case beneath the aluminum post.

Deposit marked stone alongside the aluminum post.

Retain the L-angle iron fence post north of the aluminum post.

Corner is located on level ground; rocky, clay soil; dense sagebrush and sparse grasses.

N. 0°07.5' W., beginning new measurement.

- 40.038** Point for the corner of sections 1, 2, 11, and 12, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 27 inches in the ground, with aluminum cap marked

T9S R4W  
S2 | S1  
S11 | S12  
2014

Deposit a magnet in a plastic case beneath the aluminum post.

Set a steel fence post east of the aluminum post.

Corner is located on the northeast edge of a small drainage, drains northwesterly; sandy soil; sagebrush and grass.

From this corner, the corner of sections 2, 3, 10, and 11, bears N. 89°54.2' W., 80.170 chains distance, monumented by Francis D. Eickbush, in 2005, (plat 2005-0029-01) with an aluminum pipe, 2 1/2 inches diameter, firmly set, projecting 12 inches above the ground, in a scattered mound of stone, with aluminum cap marked EICKBUSH & ASSOCIATES T9S R4W S2 S3 S10 S11 LS317443 2005, with an L-angle fence post along west side, and at a corner of abandoned fences extending north and east. This position is accepted as the best available evidence of the position of the original corner.

This control line was fully retraced and careful search was made for evidence of the intervening corner, none of which was found.

From this same corner, a cedar post, 6-inches diameter, projecting 10 inches above the ground, for the corner of abandoned fences extending north and west, bears N. 7°25.7' E., 19.3 links

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

distance.

From this same corner, a corner of new fences extending north and west, bears N.  $8^{\circ}05.8'$  W., 29.5 links distance.

---

From the corner of sections 1 and 12 only, on the east boundary of the township, hereinbefore described.

S.  $89^{\circ}23.5'$  W., between sections 1 and 12.

- 40.220** The 1/4 section corner of sections 1 and 12, monumented with a broken quartzite stone, 10x9x5 inches (Record, 16x9x6 inches), loosely set, marked 1/4 on a face.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 25 inches in the ground, in a small collar of stone, with aluminum cap marked

T9S R4W

	S1
1/4	-----
	S12
	2014

Deposit a magnet in a plastic case beneath the aluminum post.

Deposit marked stone alongside the aluminum post.

Set a steel fence post east of the aluminum post.

Corner is located on level ground; sandy soil; dense sagebrush.

---

S.  $89^{\circ}05.8'$  W., beginning new measurement.

- 40.313** The corner of sections 1, 2, 11, and 12.
- 

N.  $0^{\circ}06.2'$  W., between sections 1 and 2.

- 40.038** Point for the 1/4 section corner of sections 1 and 2, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 27 inches in the ground, with aluminum cap marked

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH  
CHAINS

T9S R4W  
1/4  
S2 | S1  
2014

Deposit a magnet in a plastic case beneath the aluminum post

Corner is located 5 links east of a barbed-wire fence, 4-strand, bears north and south; and 40 links south of the projection of an abandoned fence from the east.

- 80.476** The corner of sections 1, 2, 35, and 36, on the north boundary of the township, hereinbefore described.

---

Subdivision of Section 1,  
T. 9 S., R. 4 W., Salt Lake Meridian, Utah

---

From the 1/4 section corner of sections 1 and 12.

**N. 0°12.6 W.**, on the north-south centerline of section 1.

- 39.843** Point for the center 1/4 section corner of section 1, at intersection with the east-west centerline.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 27 inches in the ground, with aluminum cap marked

T9S R4W  
C1/4 S1  
2014

Deposit a magnet in a plastic case beneath the aluminum post.

Set a steel fence post along southwest side of the aluminum post.

Corner is located in an abandoned fence, bears east and west, on level ground; dense sagebrush and sparse grass.

- 80.018** The 1/4 section corner of sections 1 and 36, on the north boundary of the township, hereinbefore described.

---

From the 1/4 section corner of section 1 only, on the east boundary of the township, hereinbefore described.

**S. 89°22.4' W.**, on the east-west centerline of section 1.

- 40.066** The center 1/4 section corner of section 1.

- 80.298** The 1/4 section corner of sections 1 and 2.

SUBDIVISION OF SECTION 25,  
TOWNSHIP 9 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

---

Subdivision of Section 25,  
T. 9 S., R. 4 W., Salt Lake Meridian, Utah

---

From the 1/4 section corner of sections 25 and 36.

**N. 0°41.3' E.**, on the north-south centerline of section 25.

- 40.221** Point for the center 1/4 section corner of section 25, at intersection with the east-west centerline.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 25 inches in the ground, with aluminum cap marked

T9S R4W  
C 1/4 S25  
2014

Deposit a magnet in a plastic case beneath the aluminum post.

Set a steel fence post along northeast side of the aluminum post.

Corner is located on level ground; clay soil; scattered pinon and juniper; dense sagebrush.

- 80.698** The 1/4 section corner of sections 24 and 25.
- 

From the 1/4 section corner of section 25 only, on the east boundary of the township, hereinbefore described.

**N. 89°51.0' W.**, on the east-west centerline of section 25.

- 40.775** The center 1/4 section corner of section 25.

- 81.220** The 1/4 section corner of sections 25 and 26.
-

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**FIELD ASSISTANTS**

---

Name	Capacity
Matthew N. Gillins	Survey Technician
Frazier Hansel	Survey Aide
Jacob Murdoch	Student Trainee

---

## CERTIFICATE OF SURVEY

I, **Matthew J. Kurchinski, Cadastral Surveyor**, HEREBY CERTIFY upon honor, that in pursuance of Special Instructions bearing the date of the **20<sup>th</sup> day of September, 2013**, and Supplemental Special Instructions bearing the date of the **2nd day of May, 2014**, I have **dependently resurveyed a portion of the east boundary, a portion of the north boundary, and a portion of the subdivisional lines, and have subdivided sections 1 and 25, in Township 9 South, Range 4 West**, of the **Salt Lake Meridian**, in the State of **Utah**, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said Special Instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

22-Jan-2016

Date

Matthew J. Kurchinski

Cadastral Surveyor

## CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT  
Salt Lake City, Utah

The foregoing field notes of **the dependent resurvey of a portion of the east boundary, a portion of the north boundary, and a portion of the subdivisional lines, and the subdivision of sections 1 and 25, in Township 9 South, Range 4 West, Salt Lake Meridian, Utah**, executed by **Matthew J. Kurchinski, Cadastral Surveyor**, having been critically examined and found correct, are hereby approved.

January 25, 2016

Date

Daine W. Webb

Chief Cadastral Surveyor for Utah